ENERGY AND MINERALS DEPARTMENT

DISTRIBUTION	Ĭ.	Ĭ.	
SANTA PE	Ŀ		
FILE			
V.S.G.S.			
LAND OFFICE			
000000	T =		

OIL CONSERVATION DIVISION P.O. BOX 2088 SANTA FE, NEW MEXICO 87501

Form C-103 Revised 19-1-7

(DO NOT USE THIS PORM FOR PROPOSALS TO USE "APPLICATION FOR PE	CES AND REPORTS ON WELLS DRILL OR TO DEEPEN OF PLUE BACK TO A DIFFERENT RESERVOIR. BMIT (FORM C-101) FOR SUCH PROPOSALS.)	Sa. Indicate Type of Lease State X Fee 5. State Oil & Gas Lease No. E-316 7. Unit Agreement Name			
. 2. Name of Operator	•	8. Form or Lease Hame			
ARCO Oil and Gas Company	State "G" TG				
P. O. Box 1610, Midland, Tex	as 79702	9. Well No.			
4. Location of Well		10. Fleid and Pool, or Wildcat			
UNIT LETTER D 330	PEET PROM THE NORTH LINE AND 990 PEE	E-K Yates-SR-Oueen			
THE West LINE, SECTION 2	. mon.				
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County			
	3917' DF	Lea			
NOTICE OF INTENTIC	Nate Box To Indicate Nature of Notice, Report of	or Uther Data DUENT REPORT OF:			
PERFORM REMEDIAL WORE TEMPORARILY ABANDON PULL OR ALTER CABING	PLUG AND ABANDON X REMEDIAL WORK COMMENCE DRILLING OPMS. CHANGE PLANS CABING TEST AND CEMENT JQB OTHER	ALTERING CASING PLUG AND ASANDONMENT			
17. Describe Proposed or Completed Operations (work) SEE RULE 1103.	Clearly state all pertinent details, and give pertinent dates, inc	cluding estimated date of starting any propose			
circulated f/500' (remedial	sx - TOC 2080' - calculated (primary jo	0' w/30' cement on top.			
Plug <u>Interval</u> <u>Cement</u> 1 3450-3415 5 sx	Remarks CIBP @ 3450'. Dump bail 5 sx cement on top (35'). Cover Yates perfs 3485-3522'.				
*2 3025-2778 25 sx	Spot. Cover Base of Salt @ 2925'.				
3 1600-1862 80 sx	Perf 5-1/2" casing @ 1862' w/4 holes. Cement under CICR @ 1600'. Cover Top of Salt @ 1862' and surface casing shoe @ 1661'.				
18. I hereby certify that the information above is t	rue and complete to the best of my knowledge and belief.				
11000 William C Hear	915-688-5329 Sr. Drilling Engineer	May 18, 1988			
ORIGINAL SIGNED BY JERRY SEXTO	71716	MAY 2 3 1988			

State "G" TG #2 Proposed P & A Page Two

Plug	Interval	Cement	Remarks	
		25 sx	Spot. Cov	er holes in $5-1/2$ " casing @ 500'.
5	10-0	3 sx	Spot. Sur	face plug.

Cut off casing 3' below ground level. Install P & A marker. Reclaim location. *Circulate hole w/10 ppg mud (25 ppb gel).

