

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. NM-569
7. Lease Name or Unit Agreement Name BRIDGES STATE
8. Well No. 92
9. Pool name or Wildcat VACUUM GRAYBURG SAN ANDRES
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4057 GL 4070 KB

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER
2. Name of Operator Mobil Producing Tx. & N.M. Inc.*
3. Address of Operator *Mobil Exploration & Producing U.S. Inc., as Agent for Mobil Producing TX. & N.M. Inc., P. O. Box 633, Midland, TX 79702
4. Well Location Unit Letter O : 660 Feet From The SOUTH Line and 1980 Feet From The EAST Line Section 3 Township 17S Range 34E NMPM LEA County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6/6/91 - MIRU MAYO MARRS. POOH W/RODS & PUMP. ND WELLHEAD. NU BOP.

6/7/91 - PU & GIH W/BAKER CMT RTNR. SET @ 4600. STING OUT & CIRC HOLE W/BRINE. LOAD TBG W/55 SXS CL C CMT. STING INTO RTNR & PUMP 45 SXS CMT. STING OUT & PUMP 10 SXS ABOVE RTNR. POOH & LD 92 JTS TO 1750. PUMP 25 SXS CL C CMT. POOH & LD WS. WOC. TAG PLUG @ 1530 W/SL. PUMP 5 SXS SURF PLUG. CUT OFF WH, WELD ON CAP & INSTALL P&A MARKER. RDMO.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE

Engineering Technician

DATE 6/13/91

TYPE OR PRINT NAME

J. W. DIXON

(915)

TELEPHONE NO. 688-2452

(This space for State Use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL IF ANY:

OIL & GAS INDUSTRY NEW MEXICO 1991