

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State ☒	Fee ☐
5. State Oil & Gas Lease No. B-1520	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☐ GAS WELL ☐ OTHER- <u>WIW</u>		7. Unit Agreement Name
2. Name of Operator <u>Mobil Oil Corporation</u>		8. Farm or Lease Name <u>Bridges State</u>
3. Address of Operator <u>Three Greenway Plaza East, Suite 800, Houston, Texas 77046</u>		9. Well No. <u>40</u>
4. Location of Well UNIT LETTER <u>A</u> <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>East</u> LINE, SECTION <u>14</u> TOWNSHIP <u>17S</u> RANGE <u>34E</u> NMPM.		10. Field and Pool, or Wildcat <u>Vac. Grayburg/S. A.</u>
15. Elevation (Show whether DF, RT, GR, etc.) <u>4038 GR</u>		12. County <u>Lea</u>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐
PULL OR ALTER CASING ☐	OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐	ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOBS ☐	OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Please see attachment for proposed procedure.

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED A.R. Aring TITLE Authorized Agent DATE 12/21/77

APPROVED BY _____ TITLE _____ DATE 12/21/77

CONDITIONS OF APPROVAL, IF ANY:

HOUSTON E & P DIVISION-WEST

WELL WORK RECOMMENDATIONS

Proposals for Well Reconditioning and Subsurface Maintenance
Workovers, Expense DD's, PB's, and Conversions

Lease Bridges State Well No. 40 wiw

Field Vacuum Grayburg / San Andres

County Lea State New Mexico

RECOMMENDED PROCEDURE

- 1) Set 7" cmt retainer on 2 $\frac{3}{8}$ " work string @ 4200' $\pm$
- 2) Squeeze open hole (4400'-4755') w/190 sx Class "C" neat cmt
- 3) Spot a 35' plug on retainer w/6 sx cmt
- 4) Load hole w/ mud "laden fluid, using 25 lbs gal / 1000 gals
(min density should be 9.5 lbs/gal)
- 5) Spot a 100' plug across the salt base (2685'-2785')
w/17 sx cmt
- 6) Perforate 7" csq @ 1000'-1002'; 4JSPF Bleed down
all pressure and water flow that may result from perforating.
Set 7" cmt retainer @ 950' and attempt to circ cmt to surface
w/ 250 sx cmt.
- 7) Spot a 35' plug on retainer w/ 6 sx cmt
- 8) Spot a 20' plug @ surface w/4 sx cmt
- 9) Erect a P&A monument
- 10) Clear location

Note: * Procedure verbally approved by Jerry Sexton (NMOCCL)
* Notify NMOCCL (505) 393-6161 24 hrs prior to P&A

Well: Vacuum G/Son Andrus	Date 11/14/77	T/A Date 10/20/76
Lease: Bridges State	No 40	County & State Lea, New Mexico
Location: A/S14/T175/R34E	Completion Date: 9/39'	Elev. KA Elev

