

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. NA 30-025-02033
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-1520
7. Lease Name or Unit Agreement Name BRIDGES STATE
8. Well No. 54
9. Pool name or Wildcat VACUUM GRAYBURG SAN ANDRES
10. Elevation (Show whether DP, RKB, RT, GR, etc.) 4025 GL

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator
Mobil Producing Tx. & N.M. Inc.*

3. Address of Operator *Mobil Exploration & Producing U.S. Inc., as Agent for
Mobil Producing TX. & N.M. Inc., P. O. Box 633, Midland, TX 79702

4. Well Location
Unit Letter P : 660 Feet From The SOUTH Line and 660 Feet From The EAST Line

Section 14 Township 17S Range 34E NMPM LEA County

10. Elevation (Show whether DP, RKB, RT, GR, etc.)
4025 GL

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5/24/91 - RIH W/PKR ON 2-3/8 TBG. SET PKR 4065 TO CIBP 4144' TO 1000#/HELD OK. PRESS TEST CSG TO 750#/HELD O.K.. CONSULTED W/JERRY SEXTON-NMOC DIR. GAVE PERMISSION TO SET CMT PLUGS IN CSG/CONTINUE W/JOB. SPOT 30 SXS CL C 4144-3944. PULLTED TBG TO 1650-SPOT 40 SXS CL C CMT FROM 1650-1550. POH W/TBG.

5/27/91 - STACKED OUT TBG/ND BOP. RIH & CUT 7 CSG AT 851. SECURED WELL.

5/29/91 - POH AND LAID DOWN TBG. SPOT 60 SXS CLS C CMT FROM 900' TO CAL TOP =700 FT. POH W/TBG.

5/30/91 - RIH W/TBG. TAGGED TOP OF CMT @ 770 (130 CMT PLUG) ok/ED BY RAY SMITH-NMOCD SUPERV. POH W/TBG/LAID DOWN TBG TOOLS. CLEANED OUT CELLAR - SET 5 SXS CMT AT SURFACE AND INSTALLED P&A MARKER. RIG DOWN AND REL MARRS CSG PULLER #2. WELL P&A 5/30/91. FINAL REPORT.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. W. Dixon TITLE Engineering Technician DATE 6/10/91
(915)
TYPE OR PRINT NAME J. W. DIXON TELEPHONE NO. 688-2452

(This space for State Use)

APPROVED BY Johnny Robinson TITLE _____ DATE 6/25/91
CONDITIONS OF APPROVAL, IF ANY: _____