STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES ACCEIVED	
DISTRIBUTION	
SANTA PE	
プリレ ヹ	
U.S.G.S.	
LAND OFFICE	
OPERATOR	l

CONDITIONS OF APPROVAL AFTANYS

OIL CONSERVATION DIVISION

P. O. BOX 2088

	• •	J. 15 J.		
SANTA	FE.	NEW	MEXICO	87501

Form C-103 - Revised 10-1-78

FILE	5a. Indicate Type of Lease					
U.S.G.S.	State X Fee					
LAND OFFICE	5. State Oil & Gas Lease No.					
OPERATOR	В-1080					
SUNDRY NOTICES AND REPORTS ON WELLS	VIIIIIIIIIIIII					
SUNDRY NOTICES AND REFORM FOR PROPOSALS TO DEFLUE ON TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. (DO NOT USE THIS FORM FOR PROPOSALS TO DEFLUE ON TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-1011 FOR SUCH PROPOSALS.)	VIIIIIIIIIIII					
	Vacuum Grayburg					
OIL GAS OTHER-	San Andres Unit					
. Name of Operator	8. Farm or Lease Name Vacuum Grayburg					
Texaco Inc.	San Andres Unit					
. Address of Operator	lin.					
P.O. Box 728, Hobbs, New Mexico 88240	LO Field and Pool, or Wildcat					
	Vacuum Grayburg					
UNIT LETTER F 1980 FEET FROM THE NORTH LINE AND 1980 FEET FROM	Self Hill Friends					
THE West LINE, SECTION 1 TOWNSHIP 18-S RANGE 34-E NMPM						
15. Elevation (Show whether DF, RT, GR, etc.)	12. County					
4003' (DF)	Lea					
Check Appropriate Box To Indicate Nature of Notice, Report or Ot	her Data					
NOTICE OF INTENTION TO: Check Appropriate Box To indicate Nature of Notice, representation of N	T REPORT OF:					
NOTICE OF INTENTION 10.	L7					
PERFORM REMEDIAL WORK	ALTERING CASING					
TEMPORARILY ABANDON COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT					
CARLING TEST AND CEMENT JOB	ater Flow XX					
OTHER REPORTS	4					
OTHER						
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including	g estimated date of starting any proposed					
work) SEE RULE 1103.						
1. Rigged up. Install BOP. Pull submersible pump.						
2. Set RBP @ 3900' & spot 20' sand on plug.						
3. Perforate 7" csg. w/2-JS @ 1565'.						
1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -						
4. Set cement retainer @ 1495'. Cement peris @ 1505' W/	t hold. Unable to					
pump into perfs @ 1565'.						
pump into peris & 1909.						
5. Perforate 7" csg. w/2-JS @ 1400'.	Perforate 7" csg. w/2-JS @ 1400'.					
	a altaga deser					
6. Set cement retainer @ 1335'. Cement squeeze 7" perfs	(@ 1400' w/75 sx.					
diaga tot coment conteining 2% Cacl. Ran Temperature	Survey. Noc. Doc.					
Tested csg to 600# for 30 minutes, 11:00-11:30 AM, 4-	29-02. Tested Ok.					
7. Pull RBP & install production equipment. Test & retu	rn to production.					
7. Pull RBP & install production equipment. Test a rest	The production of the producti					
18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.						
Asst. Dist. Manager	5-14-82					
SIGHED TITLE						
morning a market be and	MAN. 1 0 1000					
ORTOTALL SOCIETAL TITLE	DATE MAY 10 1982.					
APPHOYED BY						