

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State ☒ F

5. State Oil & Gas Lease No.
B-3011

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
SEE INSTRUCTIONS FOR PERMIT UNDER C-101 FOR SUCH PROPOSALS.)

1. OIL ☒ WELL GAS ☐ WELL OTHER ☐

2. Name of Operator
Texaco Inc.

3. Address of Operator
P.O. Box 728, Hobbs, New Mexico 88240

4. Location of Well
UNIT LETTER D 660 FEET FROM THE North LINE AND 660 FEET FROM
THE West LINE, SECTION 2 TOWNSHIP 18-S RANGE 34-E N.M.P.M.

15. Elevation (Show whether DF, RT, GR, etc.)
4047.63

7. Unit Agreement Name
Vacuum Grayburg
San Andres Unit

8. Form or Lease Name

9. Well No.
51

10. Field and Pool, or Valued
Vacuum Grayburg
San Andres

12. County
Lea

11. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☒	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	
		OTHER ☐	

12. Description of Operations to be Completed Operations to clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. SEE RULE 1103

- 1) Run in full production equipment
 - 2) Cleanout to TD and drill new hole to 4756'
 - 3) Run GR/CNL/caliper from 4756-3684
 - 4) Analyze with 10,000 galb 15% gelled WFFF
 - 5) Run production equipment and test
- PAWD 131.30 70BW
PBWD 157.30 68BW

13. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED A. Gernandt TITLE Area Superintendent DATE MAY 4 1987

A. Gernandt (393-4031)

APPROVED BY _____ TITLE _____

CONDITIONS **ORIGINAL SIGNED BY JERRY SEXTON**
DISTRICT I SUPERVISOR