

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR INFORMATION TO BE USED IN THE DETERMINATION OF RESERVE DATA TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT TO DRILL OR RE-ENTER EXISTING WELLS FOR DEPOSIT.)			
1. OIL WELL ☒ CAS WELL ☐ OTHER- _____		11. Unit Agreement Name Vacuum Grayburg San Andres Unit	
2. Name of Operator TEXACO Inc.		12. Well No. 52	
3. Address of Operator P.O. Box 728 Hobbs, New Mexico 88240		13. Field, Lease, or Well No. Vacuum Grayburg San S Andres	
4. Location of Well UNIT LETTER <u>C</u> <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM THE <u>West</u> LINE, SECTION <u>2</u> TOWNSHIP <u>18-S</u> RANGE <u>34-E</u> N.M.P.M.		14. Elevation (Show whether DT, RT, GR, etc.) 4027' (DF)	
15. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:		16. County Lea	
PERFORM REMEDIAL WORK ☐ TEMPORARILY ABANDON ☐ PULL OR ALTER CASING ☐ OTHER _____ ☐		PLUG AND ABANDON ☐ CHANGE PLANS ☐ OTHER _____ ☐	
PERFORM REMEDIAL WORK ☒ COMMENCE DRILLING OPNS. ☐ CASING TEST AND CEMENT JOBS ☐ OTHER _____ ☐		ALTERING CASING ☐ PLUG AND ABANDONMENT ☐ OTHER _____ ☐	
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.			

1. Rigged up. Pull rods and pump. Pull tubing.
2. Clean out to 4696' (PBTD).
3. Set pkr @ 3997' Acidize open-hole 4187-4696' w/5000 gal 15% NE Acid in 5-equal stages using 1000# rock salt & 500# Benzoic Acid Flakes between stages.
4. Install pumping equipment
5. Test and return to production.

hereby certify that the information above is true and complete to the best of my knowledge and belief.

FD-36 (Rev. 5-22-64)

TO: J. L. Caffery TITLE: Asst. Dist. Supt. DATE: 9-22-78

ORIG. SIGNED BY: John Ruyvan TITLE: _____ DATE: SEP 23 1978

COPIES OF APPROVAL, IF ANY: _____