## OIL CONSERVATION COMMIS ) Santa Fe, New Mexico

REQUEST FOR (OIL)-(GAS) ALLOWABLE

It is necessary that this form be submitted by the operator before an initial allowable will be assigned to any completed oil or gas well. Form C-110 [Certificate of Compliance and Authorization to Transport 0il) will not be approved until form C-101 is filled with the Commission. Form C-104 is to be submitted in triplicate to the office to which form C-101 was sent. Two copies will be retained there and the other submitted to the Proration Office, Hobbs. New Mexico. The allowable will be assigned effective 7:00 a.m. on date of completion, provided completion report is filled during month of completion. The completion date shall be that date in the case of an oil well when oil is delivered into the stock tanks. Gas must be reported on 15.025 P.B. at  $60^{\circ}$  Fahrenheit.

u <sub>o</sub> ;	hhe New Merrico	hmam 13 1052	
Pla	bbs, New Mexico Fe	Date	
CARE HEREBY REQUESTING	AN ALLOWABLE FOR A WELL KNOWN :	AS:	
			1 - 1
Company or Operation	Lea State MVM Hell No	0. <u> </u>	1 / 1
ection 3 , T. 185,	R. 34E N.M.P.M. Vacuum	Pool Les	County
lease indicate location:	Elevation 40221 Spudded	12-5-51 Completed 2-13	-52
	Total Depth 4710'		
	Top Uil/Gas Pav 45201	Ton Water Day	
	Initial Production Test: Pum	p_ <b>32</b> Flow(	ROPD OR CL. FT.
	Based on 32 Bbls. Oil in		
	Method:of Test (Pitot, gauge		
	· ·		_
	Size of choke in inches		
	Tubing (Size) 2-3/8"	46891	leet
	Pressures: Tubing Name	Casing <b>10#</b>	
·	Gas/Oil Ratio Not taken	Gravity <b>31</b>	
	Casing Pe	erforations:	
· · · · · · · · · · · · · · · · · · ·	None		
mit letter: <b>I</b>			d water
	Acid Record:	Show of Oil.Gas and	_
	Acid Record: 	Show of Oil.Gas and S/ Swabbed 49 bbls	oil in 23
	Acid Record:	Show of Oil.Gas and S/ Swabbed 49 bbls  S/ Swabbed 25 bbls	oil in 23
sing & Cementing Record Size Feet Sax	Acid Record:	Show of Oil.Gas and S/ Swabbed 49 bbls S/ Swabbed 25 bbls S/	oil in 23
asing & Cementing Record	Acid Record:	Show of 011.6as and 5/ Swabbed 49 bbls 5/ Swabbed 25 bbls 5/ 5/ 5/ 5/ 5/ 5/ 5/ 5/ 5/ 5/ 5/ 5/ 5/	oil in 23
Size Feet Sax  2-5/8 1677 700	Acid Record:  3000 Gals 4550 to 4700 5000 Gals 4515 to 4700 Gals to 5000 Shooting Record.	Show of 011.Gas and S/ Swabbed 49 bbls S/ Swabbed 25 bbls S/	oil in 23]
asing & Cementing Record Size Feet Sax	Acid Record:  3000 Gals 4550 to 4700 5000 Gals 4515 to 4700 Gals to 5000 Shooting Record.  Qts to 5000	Show of 011.Gas and 5/ Swabbed 49 bbls 5/ Swabbed 25 bbls 5/	oil in 23]
Size Feet Sax  8-5/8 1677 700	Acid Record:  3000 Gals 4550 to 4700 5000 Gals 4515 to 4700 Gals to 5000 Shooting Record.  Ots to 5000 Uts to 5000 None Qts to 5000	Show of 011.Gas and S/ Swabbed 49 bbls S/ Swabbed 25 bbls S/	oil in 23
Size Feet Sax  2-5/8* 1677* 700	Acid Record:  3000 Gals 4550 to 4700 5000 Gals 4515 to 4700 Gals to 5000 Shooting Record.  Qts to 5000	Show of 011.Gas and S/ Swabbed 49 bbls S/ Swabbed 25 bbls S/	oil in 23 oil in 6 l
Size Feet Sax  8-5/8 1677 700	Acid Record:  3000 Gals 4550 to 4700 5000 Gals 4515 to 4700 Gals to 5000 Shooting Record.  Qts to 5000 Qts to 5000 Natural Production Test:	Show of Oil.Gas and S/ Swabbed 49 bbls S/ Swabbed 25 bbls S/ Mone Pumping None	oil in 23
Size Feet Sax  2-5/8* 1677* 700	Acid Record:  3000 Gals 4550 to 4700 5000 Gals 4515 to 4700 Gals to 5000 Shooting Record.  Ots to 5000 Uts to 5000 None Qts to 5000	Show of Oil.Gas and S/ Swabbed 49 bbls S/ Swabbed 25 bbls S/ Mone Pumping None	oil in 23
<b>8</b> -5/8* 1677* 700 5-1/2* 4335* 400	Acid Record:  3000 Gals 4550 to 4700 5000 Gals 4515 to 4700 Gals to 5000 Shooting Record.  Qts to Qts to None Qts to  Yatural Production Test:  Test after acid or shot:	Show of Oil.Gas and S/ Swabbed 49 bbls S/ Swabbed 25 bbls S/ S/ S/ S/ S/ S/ S/ S/ S/ Pumping None 132 Pumping	oil in 232 oil in 6 1
Size Feet Sax  8-5/8* 1677* 700  5-1/2* 4335* 400  lease indicate below For	Acid Record:  3000 Gals 4550 to 4700 5000 Gals 4515 to 4700 Gals to 5000 Shooting Record.  Qts to 5000 Qts to 5000  Natural Production Test: 5000  Test after acid or shot: 5000  mation Tops(in conformance with	Show of Oil.Gas and S/ Swabbed 49 bbls S/ Swabbed 25 bbls S/ S/ S/ S/ S/ S/ S/ S/ S/ Pumping None Pumping None h geographical section	oil in 23 oil in 6 l Flowing Flowing
Size Feet Sax  2-5/8* 1677* 700  5-1/2* 4335* 400  lease indicate below For	Acid Record:  3000 Gals 4550 to 4700 5000 Gals 4515 to 4700 Gals to 5000 Shooting Record.  Qts to Qts to None Qts to  Yatural Production Test:  Test after acid or shot:	Show of Oil.Gas and S/ Swabbed 49 bbls S/ Swabbed 25 bbls S/ S/ S/ S/ S/ S/ S/ S/ S/ Pumping None 132 Pumping	oil in 23 oil in 6 l Flowing Flowing
Size Feet Sax  2-5/8 1677 700  5-1/2 4335 400  lease indicate below For	Acid Record:  3000 Gals 4550 to 4700 5000 Gals 4515 to 4700 Gals to 5000 Shooting Record.  Qts to 5000 Qts to 5000  Natural Production Test: 5000  Test after acid or shot: 5000  mation Tops(in conformance with	Show of Oil.Gas and  S/ Swabbed 49 bbls  S/ Swabbed 25 bbls  S/  S/  S/  S/  S/  Pumping None  Northwestern New Me  T. Ojo Alamo	oil in 23 oil in 6 l Flowing Flowing of state):
Size Feet Sax  2-5/8 1677 700  5-1/2 4335 400  lease indicate below For Southeast  Anhy 1660	Acid Record:  3000 Gals 4550 to 4700 5000 Gals 4515 to 4700 Gals to 5000 Gals to 5000 Shooting Record.  Qts to 5000 Whene Qts to 5000 Natural Production Test: Test after acid or shot:  mation Tops(in conformance with the following should be shown to 5000 T. Devonian 5000 T. Dev	Show of Oil.Gas and  S/ Swabbed 49 bbls  S/ Swabbed 25 bbls  S/  S/  S/  S/  S/  Pumping None  Northwestern New Me  T. Ojo Alamo  T. Kirtland-Fruitland	oil in 23; oil in 6 l  Flowing Flowing of state):
Size Reet Sax  2-5/8 1677 700  5-1/2 4335 400  lease indicate below For Southeast  Anhy 1660	Acid Record:  3000 Gals 4550 to 4700 5000 Gals 4515 to 4700 Gals to 5000 Gals to 5000 Shooting Record.  Qts to 5000 Whene Qts to 5000 Natural Production Test: Test after acid or shot:  mation Tops(in conformance with the following should be shown to 5000 T. Devonian 5000 T. Dev	Show of Oil.Gas and  S/ Swabbed 49 bbls  S/ Swabbed 25 bbls  S/  S/  S/  S/  S/  Pumping None  Pumping None  Northwestern New Me  T. Ojo Alamo  T. Kirtland-Fruitland T. Farmington	oil in 23 oil in 6 l Flowing Flowing of state):
Size Feet Sax  2-5/8 1677 700  5-1/2 4335 400  lease indicate below For Southeast  Anhy 1660 1	Acid Record:  3000 Gals 4550 to 4700 5000 Gals 4515 to 4700 Gals to 4700 Shooting Record.  Qts to 400 Qts to 400 Natural Production Test: Test after acid or shot:  mation Tops(in conformance with ern New Mexico  T. Devonian 400 T. Silurian 400 T. Montoya 400 T. Simpson 4550	Show of Oil.Gas and S/ Swabbed 49 bbls S/ Swabbed 25 bbls S/	oil in 23 oil in 6 Flowing Flowing of state):
Size Feet Sax  8-5/8 1677 700  5-1/2 4335 400  lease indicate below For Southeast  Anhy 1660: Salt Salt	Acid Record:  3000 Gals 4550 to 4700 5000 Gals 4515 to 4700 Gals 4515 to 4700 Gals 451	Show of Oil.Gas and S/ Swabbed 49 bbls S/ Swabbed 25 bbls S/	oil in 23 oil in 6 Flowing Flowing of state):
Size   Feet   Sax     Sax     Sax     Sax     Sax     Sax     Sax     Sax	Acid Record:  3000 Gals 4550 to 4700 5000 Gals 4515 to 4700 Gals to 4700 Shooting Record.  Qts to 400 Qts to 400 Natural Production Test: Test after acid or shot:  mation Tops(in conformance with ern New Mexico  T. Devonian 400 T. Silurian 400 T. Simpson 400 T. McKee 400 T. Ellenburger 4000	Show of Oil.Gas and S/ Swabbed 49 bbls S/ Swabbed 25 bbls S/	oil in 23) oil in 6
Size   Feet   Sax	Acid Record:  3000 Gals 4550 to 4700 5000 Gals 4515 to 4700 Gals to 4700 Gals to 4700 Gals to 4700 Shooting Record.  Qts to 400 Qts to 400 Natural Production Test: Test after acid or shot:  mation Tops(in conformance with ern New Mexico  T. Devonian 400 T. Silurian 400 T. Simpson 400 T. McKee 400 T. Ellenburger 400 T. Gr. Wash	Show of Oil.Gas and  S/ Smabbed 49 bbls  S/ Smabbed 25 bbls  S/  S/  S/  S/  S/  S/  Pumping None  Rection  Northwestern New Me  T. Ojo Alamo  T. Kirtland-Fruitland T. Farmington T. Pictured Cliffs T. Cliff House T. Menefee T. Point Lookout	oil in 23 oil in 6 Flowing Flowing of state):
Size   Reet   Sax     Sax   Sa	Acid Record:  3000 Gals 4550 to 4700 5000 Gals 4515 to 4700 Gals to Shooting Record.  Qts to Qts to Matural Production Test: Test after acid or shot:  mation Tops(in conformance with term New Mexico  T. Devonian T. Silurian T. Montoya T. Simpson T. McKee T. Ellenburger T. Gr. Wash T. Granite	Show of Oil.Gas and  S/ Swabbed 49 bbls  S/ Swabbed 25 bbls  S/  S/  S/  S/  S/  Pumping None  Pumping None  Northwestern New Me  T. Ojo Alamo  T. Kirtland-Fruitland T. Farmington T. Pictured Cliffs T. Cliff House T. Menefee T. Point Lookout T. Mancos	oil in 23 oil in 6 Flowing Flowing of state):
### Size   Feet   Sax    ### Sax   Feet   Sax    ### Say   Feet   Say    ### S	Acid Record:  3000 Gals 4550 to 4700 5000 Gals 4515 to 4700 Gals to 5000 Gals 5000 to 5000 Gals 5000 Gals 5000 to 5000 Gals 5000 Gals 5000 to 5000 to 5000 Shooting Record.  Gals 5000 Gals 5000 4700 Gals 5000 to 5000 5000 Gals 6500 to 6000 Gals 6500 to 6000  Shooting Record.  Gals 5000 to 6000  To 6000 Gals 6500 to 60	Show of Oil.Gas and  S/ Swabbed 49 bbls  S/ Swabbed 25 bbls  S/  S/  S/  S/  S/  Pumping None  Pumping None  1. Ojo Alamo T. Kirtland-Fruitland T. Farmington T. Pictured Cliffs T. Cliff House T. Menefee T. Point Lookout T. Mancos T. Dakota	oil in 23
Size   Feet   Sax	Acid Record:  3000 Gals 4550 to 4700 5000 Gals 4515 to 4700 Gals to 5000 Gals 5000 Shooting Record.  Qts to 5000 Qts to 5000 Natural Production Test: Test after acid or shot:  Test after acid or shot:  Test after acid or shot:  The New Mexico 5000 The Devonian 5000 The Silurian 5000 The Montoya	Show of Oil.Gas and  S/ Swabbed 49 bbls  S/ Swabbed 25 bbls  S/  S/  S/  S/  S/  Pumping None  Pumping None  Northwestern New Me  T. Ojo Alamo  T. Kirtland-Fruitland T. Farmington T. Pictured Cliffs T. Cliff House T. Menefee T. Point Lookout T. Mancos T. Dakota T. Morrison	oil in 23
Size   Feet   Sax	Acid Record:  3000 Gals 4550 to 4700 5000 Gals 4515 to 4700 Gals to 5000 Gals 5000 Shooting Record.  Gals 5000 Gals 5000 Gals 6000 Gals	Show of Oil.Gas and  S/ Swabbed 49 bbls  S/ Swabbed 25 bbls  S/  S/  S/  S/  Pumping None  Pumping None  Northwestern New Me  T. Ojo Alamo  T. Kirtland-Fruitland  T. Farmington  T. Pictured Cliffs  T. Cliff House  T. Menefee  T. Point Lookout  T. Mancos  T. Dakota  T. Morrison  T. Penn	oil in 23; oil in 6
sing & Cementing Record  Size Feet Sax  2-5/8 1677 700  5-1/2 4335 400  lease indicate below For Southeast  Anhy 1660! Salt Salt Yates 2990! 7 Rivers 3970! Grayburg 4285! San Andres Glorieta Drinkard	Acid Record:  3000 Gals 4550 to 4700 5000 Gals 4515 to 4700 Gals to 5000 Gals 5000 Gal	Show of Oil.Gas and  S/ Swabbed 49 bbls  S/ Swabbed 25 bbls  S/  S/  S/  S/  Pumping None  Pumping None  Northwestern New Me  T. Ojo Alamo  T. Kirtland-Fruitland  T. Farmington  T. Pictured Cliffs  T. Cliff House  T. Menefee  T. Point Lookout  T. Mancos  T. Dakota  T. Morrison  T. Penn	oil in 23) oil in 6

on a production basi	is effective February 13, 1952.
	Gulf Oil Corporation Company or Operator
	By: Colorand
	Position: Ass. Area Prod. Supt.
Send communications rega	arding well to:
	Name: Gulf Oil Corporation
	Address: Box 2167, Hobbs, New Mexic
APPROVED	2-14,1962-
OIL CON	SERVATION COMMISSION

i u