

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION

XX

B-1446

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN A WELL. IT IS EFFECTIVE FOR USE AS APPLICATION FOR PERMIT TO DRILL OR TO DEEPEN A WELL.

West Vacuum Unit

West Vacuum Unit

46

Vacuum Grayburg
San Andres

Lea

1. Name of Operator
TEXACO Inc.

2. Address of Operator
P. O. Box 728, Hobbs, New Mexico 88240

3. Location of Well
UNIT LETTER **A** **660** FEET FROM THE **North** **660**
THE **West** LINE, SECTION **3** TOWNSHIP **18-S** RANGE **34-E**

4. Elevation (Show whether DF, RT, or GR)
4031' (GR)

Check Appropriate Box To Indicate Nature of Work
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	OTHER ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	CASING TEST ☐
PULL OR ALTER CASING ☐	OTHER ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details of work) SEE RULE 1103.

1. Rigged up. Pulled pumping equipment.
2. Set packer @ 4200'.
3. Spot 250 gal. Xylene & 750 gal 15% NE Acid over open hole 4234'-4773'.
4. Acidize open hole 4234'-4773' w/3000 gal. 15% gel NE Acid in 3 equal stages using 900# rock salt between stages. Flush w/25 Bbl. fresh water.
5. Treat w/165 gal. T-552 scale inhibitor. Flush w/140 Bbl. SaH water.
6. Install pumping equipment. Test & return to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge.

SIGNED [Signature] TITLE **Asst. Dist. Supt.**

1-5-77

APPROVED BY _____ TITLE _____

CONDITIONS OF APPROVAL, IF ANY:

JAN 12 1977