

NEW MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

HOBBS OFFICE OCC

MISCELLANEOUS NOTICES

Submit this notice in TRIPLICATE to the District Office, Oil Conservation Commission, before 1960 JAN 6 2 PM 3:57 copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Notice by Checking Below

NOTICE OF INTENTION TO CHANGE PLANS		NOTICE OF INTENTION TO TEMPORARILY ABANDON WELL		NOTICE OF INTENTION TO DRILL DEEPER	
NOTICE OF INTENTION TO PLUG WELL		NOTICE OF INTENTION TO PLUG BACK		NOTICE OF INTENTION TO SET LINER	
NOTICE OF INTENTION TO SQUEEZE		NOTICE OF INTENTION TO ACIDIZE		NOTICE OF INTENTION TO SHOOT (Nitro)	
NOTICE OF INTENTION TO GUN PERFORATE		NOTICE OF INTENTION (OTHER) Sand Frac	X	NOTICE OF INTENTION (OTHER)	

OIL CONSERVATION COMMISSION
SANTA FE, NEW MEXICO

PO Box 352 - Midland, Texas

January 21, 1960 - TEXACO Inc. -

(Place)

(Date)

Gentlemen:

Following is a Notice of Intention to do certain work as described below at the

TEXACO Inc.

State of NM "X" NCT-1

Well No. 4 in 0 (Unit)

(Company or Operator)

SW 1/4 NE 1/4 of Sec. 3, T. 18-S, R. 34-E, NMPM, Vacuum Pool

Lea

County.

FULL DETAILS OF PROPOSED PLAN OF WORK
(FOLLOW INSTRUCTIONS IN THE RULES AND REGULATIONS)

TO INCREASE PRODUCTION WE PROPOSE TO DO THE FOLLOWING WORK:

1. Plug back open hole from 4680' to 4670' with 10' of hydromite to assure firm cap on cement plug.
2. Acidize open hole from 4340' to 4670' with 1000 gallons of 15% low surface tension, non-emulsion acid.
3. Swab acid residue and test.
4. Fracture open hole from 4340' to 4670' down 3" tubing with hookwall packer set at 4300' in two equal stages each of 10,000 gallons of refined oil carrying one pound of sand per gal with 1000 lbs of flaked naphthalene between stages.
5. Clean out if necessary, swab well, recover load oil, test, return well to production.

Approved....., 19.....
Except as follows:

TEXACO Inc.

Company or Operator

By.....

Position..... DISTRICT ACCOUNTANT

Send Communications regarding well to:

Approved
OIL CONSERVATION COMMISSION

By.....

Title.....

Name..... E. H. Scott

Address..... PO Box 352 - Midland, Texas