

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR INDIVIDUALS TO DRILL OR TO RE-ENTER OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT TO DRILL (FORM C-101) FOR SUCH PROPOSALS.)		5a. Indicate Type of Lease State ☒ Fee ☐ 5. State Oil & Gas Lease No. B-4188
1. ☐ OIL WELL ☐ GAS WELL ☐ OTHER- Temporarily Abandoned 2. Name of Operator Murphy H. Baxter 3. Address of Operator P. O. Box 2040 Midland, Texas 79702 4. Location of Well UNIT LETTER F 2301 FEET FROM THE North LINE AND 1650 FEET FROM THE West LINE, SECTION 6 TOWNSHIP 18S RANGE 34E N.M.P.M.	7. Unit Agreement Name N. EK Queen Unit 8. Farm or Lease Name Tract3 9. Well No. 3 10. Field and Pool, or Wildcat EK Yates 7 Rivers Queen	
15. Elevation (Show whether DF, RT, CR, etc.) 4087 GR	12. County Lea	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐ TEMPORARILY ABANDON ☐ PULL OR ALTER CASING ☐ OTHER ☐	PLUG AND ABANDON ☒ CHANGE PLANS ☐ OTHER ☐	REMEDIAL WORK ☐ COMMENCE DRILLING OPS. ☐ CASING TEST AND CEMENT JOB ☐ OTHER ☐	ALTERING CASING ☐ PLUG AND ABANDONMENT ☐
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.			

***Commission will be notified 24 hrs. prior to commencing work.**

1. CIBP has been set @ 3943'. (11-15-82)
2. Spot 35' of cement on top of CIBP.
3. Displace hole with mud-laden fluid. Close pipe rams. Test plug and casing to 500#'s.
4. Perforate 4 holes @ 1620'. (Top of anhydrite @ 1635'.) Circulate or squeeze 50 sks or sufficient cement to isolate anhydrite section. WOC.
5. Tag & test plug to 500#'s.
6. Spot cement plug 50' above and below surface casing shoe @ 320'. WOC
7. Tag plug. Cut bradenhead and weld steel plate on casing. Set P & A marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNED <u>Chuck Sledge</u>	TITLE <u>Petroleum Engineer</u>	DATE <u>8-13-87</u>	
ORIGINAL SIGNED BY JERRY SEXTON			
APPROVED BY <u>DISTRICT 1 SUPERVISOR</u>	TITLE _____	DATE <u>AUG 25 1987</u>	
CONDITIONS OF APPROVAL, IF ANY:			

RECEIVED
AUG 24 1981
OCD
HOBBS OFFICE