

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

HOBBS OFFICE O. C. C.
NEW MEXICO OIL CONSERVATION COMMISSION

JAN 13 11 21 AM '67

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. E-8539
7. Unit Agreement Name
8. Farm or Lease Name New Mexico "G" State
9. Well No. 2
10. Field and Pool, or Wildcat E. K. Queen
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- 2. Name of Operator Sunray DX Oil Company 3. Address of Operator P. O. Box 1416, Roswell, New Mexico 4. Location of Well UNIT LETTER N 1858.6 FEET FROM THE West LINE AND 660 FEET FROM THE South LINE, SECTION 7 TOWNSHIP 18S RANGE 34E NMPM.
--

15. Elevation (Show whether DF, RT, GR, etc.) 4086 (DF)

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Placed 25 sx. cmt. plug over perms at 4340'.
2. Cut off 5 1/2" csg. at 619' and pulled csg.
3. Placed 25 sx. cmt. plug in and out of 5 1/2" csg stub at 619'.
4. Placed 25 sx. cmt. plug in base of surface casing at 250'.
5. Placed 10 sx cmt plug at surface.
6. Installed dry hole marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED B.F. Brawley TITLE District Engineer DATE January 12, 1967

APPROVED BY John W. Roney TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: