			Form C-103
NO. OF COPIES RECEIVED			Supersedes Old
DISTRIBUTION	NEW MEXICO OIL CONSE	じ, じ, し・ RVATION COMMISSION	C-102 and C-103 Effective 1-1-65
SANTA FE			
FILE	JAN 24 11 52	DW DI	5a. Indicate Type of Lease
U.S.G.S.	JAN L		State X Fee
OPERATOR	- - 		5. State Oil & Gas Lease No.
OFERATOR			Unknown
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO BRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT _" (FORM C-101) FOR SUCH PROPOSALS.)			
1.			7. Unit Agreement Name
OIL X GAS WELL OTHER-			8. Farm or Lease Name
2. Name of Operator			New Mexico "H" State
Sunray DX Of 3. Address of Operator	9. Well No.		
P. O. Box 1416, Roswell, New Mexico			10. Field and Pool, or Wildcat
4. Location of Well			
UNIT LETTER	660 FEET FROM THE South	LINE AND 1980 FEET FROM	E. K. Queen
	~ 100	375	
THE East	NE, SECTION 7 TOWNSHIP 18S	RANGE 34E NMPM.	
mmmm	15. Elevation (Show whether	DF, RT, GR, etc.)	12. County
		081 G.L.	Lea
16.	Check Appropriate Box To Indicate N E OF INTENTION TO:	ature of Notice, Report or Otl	REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON		COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JQB	
	[-1	OTHER	
OTHER			
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.			
1. Loaded hole w/mud.			
2. Placed 25 sx cement plug 4404-4300 over perfs.			
3. Cut off csg. @ 997'. Pulled 5 1/2" casing.			
4. Placed cmt. plugs (25 sx each) as follows: 3230-3100, 1015-915 (in and out of csg. stub), 250-150 (in base of surface pipe) and 10 sx cmt. plug @ surface.			
5. Installed dryhole marker.			
18. I hereby certify that the	information above is true and complete to the best	of my knowledge and belief.	

B.F.Brawley THILE District Engineer