

| | |
|------------------------|--|
| NO. OF COPIES RECEIVED | |
| DISTRIBUTION | |
| SANTA FE | |
| FILE | |
| U.S.G.S. | |
| LAND OFFICE | |
| OPERATOR | |

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

| | |
|---|------------------------------|
| 5a. Indicate Type of Lease | |
| State <input checked="" type="checkbox"/> | Fee <input type="checkbox"/> |
| 5. State Oil & Gas Lease No. | |
| B-936 | |

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT L" (FORM C-101) FOR SUCH PROPOSALS.)

| | | |
|--|--|--------------------------------|
| 1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> | | 7. Unit Agreement Name |
| 2. Name of Operator | | 8. Farm or Lease Name |
| Humble Oil & Refining Company | | New Mexico BO State |
| 3. Address of Operator | | 9. Well No. |
| Box 1600, Midland, Texas 79701 | | 4 |
| 4. Location of Well | | 10. Field and Pool, or Wildcat |
| UNIT LETTER <u>P</u> <u>993</u> FEET FROM THE <u>south</u> LINE AND <u>990</u> FEET FROM | | Vacuum Abo Reef |
| THE <u>east</u> LINE, SECTION <u>12</u> TOWNSHIP <u>18-S</u> RANGE <u>34-E</u> NMPM. | | |
| 15. Elevation (Show whether DF, RT, GR, etc.) | | 12. County |
| 3989' DF | | Lea |

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOB ☐
OTHER ☐
ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

MI Baber Well Service 2-9-68. Pulled tubing. Reran tubing and set packers straddle perforations 8893-8916 and swabbed. Moved packers to straddle perforations 8823-8841 and swabbed. Flow line plugged and Lovington Field Service hot oiled flow line. Started swabbing and swabbed perforations 8823-41. Moved packers to 3783-8797 and swabbed. Moved packers 8709-8715 and swabbed. Set packer over perforations 8661 and swabbed. Pulled BOP and hooked wellhead. Ran pump and placed well back in production 2-21-68.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED R. L. Berry TITLE Unit Head DATE 3-11-68
APPROVED BY John W. Runyan TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: