

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
7. Unit Agreement Name
8. Farm or Lease Name E-K Queen Unit Tr.6
9. Well No. 6
10. Field and Pool, or Wildcat E-K Yates 7 Rivers Queen
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small>	
1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER: WIW	
2. Name of Operator Mobil Oil Corporation	
3. Address of Operator P. O. Box #633, Midland, Texas	
4. Location of Well UNIT LETTER C 660 FEET FROM THE North LINE AND 1879 FEET FROM THE West LINE, SECTION 19 TOWNSHIP 18S RANGE 33E NMPM.	
15. Elevation (Show whether DF, RT, GR, etc.)	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:	
REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER Convert to WIW <input checked="" type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4447 TD. Queen OH (4426-47)

6/25/66. MIRU Well Service Unit. Wellex ran GR-N Log 3437-4437. Perf 5½" csg in Queen sd 4405-4421 with 2 sh/ft, 32 holes. Ran 3½" sd pump. Clean-out scale. Ran Guiberson "Shorty" Tension Pkr on 2-3/8" CL tbg (142 jts). Set Pkr at 4343' w/ 14,000# tension, fiber glass anchor at 4374. Install Wellhead. Completed as WIW 6/27/66.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Authorized Agent DATE 7/25/66

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: