



STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT
OIL CONSERVATION DIVISION
HOBBS DISTRICT OFFICE

September 13, 1979

POST OFFICE BOX 1800
HOBBS, NEW MEXICO 88240
(505) 393-6161

BRUCE KING
GOVERNOR
LARRY KEHOE
SECRETARY

Mr. Bill Durham
Phillips Petroleum Company
4001 Penbrook
Odessa, Texas 79762

SUBJECT: Division Order R-5897

Gentlemen:

After re-examining the additional information submitted, it has been determined that the following wells appear to have the Grayburg-San Andres zone properly cemented off:

Phillips Petroleum Company

Vacuum Abo Unit Tr. 7 Well #4-I in Section 27, T17S, R35E
Additional information -- DV collar at 4606 feet

✓ Vacuum Abo Unit Tr. 13 Well #2-E in Section 4, T18S, R35E
Additional information -- DV collar at 4986 feet

Vacuum Abo Unit Tr. 7 Well #3-P in Section 27, T17S, R35E
Additional information -- DV collar at 4654 feet

EVGSAU Tr. 2865 Well #002-G in Section 28, T17S, R35E
Additional information -- Temperature survey showed top of cement above GB

EVGSAU Tr. 2717 Well #006-P in Section 27, T17S, R35E
Additional information -- Bond log showed bonding above GB 3910--3950'

EVGSAU Tr. 2851 Well #001-A in Section 28, T17S, R35E
Additional information -- Record of temperature log in OCD files showed top of cement above GB

The following well will still need to be re-entered as there is no cement top available for the 4½" casing, and there is no solid plug between the top of the salt and surface: Amoco, State CV Well #1-L in Section 25, T17S, R35E.

Very truly yours,

OIL CONSERVATION DIVISION

Jerry Sexton, Supervisor, Dist. I

JS/ed

cc: Joe D. Ramey - OCD Santa Fe
R.L. Stamets - OCD Santa Fe