

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P. O. Box 1980, Hobbs, NM 88240

DISTRICT II
P. O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P. O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-03016
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. B-1713
7. Lease Name or Unit Agreement Name Vacuum Abo Unit Bty 2 Tr 13
8. Well No. Tr 13 Bty 2 4
9. Pool name or Wildcat Vacuum Abo Reef

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER	
2. Name of Operator Phillips Petroleum Company	
3. Address of Operator 4001 Penbrook St., Odessa, TX 79762	
4. Well Location Unit Letter <u>B</u> : <u>330</u> Feet From The <u>North</u> Line and <u>1980</u> Feet From The <u>East</u> Line Section <u>4</u> Township <u>18-S</u> Range <u>35-E</u> NMPM <u>Lea</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3596' RKB	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
PLUG AND ABANDON ☐
CHANGE PLANS ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOB ☐
ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

12-30-88: 8791' PTD. MI & RU DDU. COOH w/rods & pump. Installed BOP. COOH w/2-3/8" tbq & TAC.

12-31-88 thru

1-03-89: Swbd to test perms 8725'-8762', rec 30 B0, 170 BW in 10 hrs. Spotted 5 bbls acetic acid from 8663'-8400'.

1-04-89: Perf'd 5-1/2" csg w/4" OD csg gun 2 SPF from 8320'-8362'; 8409'-8436'; 8442'-8446'; 8450'-8465'; 8470'-8481'; 8487'-8497'.

SEE REVERSE SIDE

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE L. M. Sanders

TITLE Reg. & Pro. Supervisor DATE 1/27/89

TYPE OR PRINT NAME L. M. Sanders

TELEPHONE NO. (Sanders) 915-367-1488

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY DISTRICT I SUPERVISOR

TITLE _____ DATE JAN 31 1989

CONDITIONS OF APPROVAL, IF ANY:

040800

040800

1-05 thru
1-16-89:

Frac'd perfs 8320'-8644' w/14,910 gals 15% FE HCl acid containing
8 gals SGA-HT, 5 gals HC-2, 10 gals FE-1A, 9 gals FE-2, 2 gals
HAI-60 and 34,790 gals CO₂ w/30# gelled and crosslinked 10# brine
and rock salt. Swbd back load. Set 2-3/8" tbg and anchor @
8140', SN @ 8773'. Set 2" X 1-1/4" X 22' pump.

1-17-89: Pmpd 24 hrs., .5 B0, 123 BW, .5 MCFG. Job complete.