

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
811 South First, Artesia, NM 87210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

WELL API NO. 30- 025-03058
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. B-2073
7. Lease Name or Unit Agreement Name: VACUUM GE/SA UNIT EAST TRACT # 0524
8. Well No. 036
9. Pool name or Wildcat VACUUM GRAYBURG SAN ANDRES

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other	2. Name of Operator Phillips Petroleum Company
3. Address of Operator 4001 Penbrook Street Odessa, TX 79762	4. Well Location Unit Letter C : 660 feet from the NORTH line and 1980 feet from the WEST line Section 5 Township 18-S Range 35-E NMPM County LEA
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3960' GL.	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐

OTHER: ACID FRAC LATERAL ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

05/11/02 MIRU WSU
05/12&13/02 CREW OFF
05/14/02 KILL POOH W/RODS/RMP ND WH NU BOP POOH W/TBG TIH W/BIT SCRPR & TBG T/4100' POOH W/TBG SCRPR & BIT TIH 20 STDS F/KS SECURE
05/15/02 KILL POOH W/KS MI 3-1/2 PH6 WS TIH TSTNG 3-1/2 PH6 TBG T/8000 PSI SECURE
05/16/02 FIN TSTNG 3-1/2 PH6 TBG TAG @ 6094' POOH W/3-1/2 PH6 TBG PERED SUB & BP TIH W/3-1/2 PH6 TBG & SPACE OUT JET SUBS THRUOUT LATERAL JET SUB #1 @ 4512' #2 4763 #3 4979' #4 5226' #5 5443' #6 5692' #7 6063' JET ON #2 JET SUB PO HUNG ON EDGE BOP ORDER ANOTHER JET F/ODESSA SD
05/17/02 FIN TIH W/JET SUBS PKR & TBG PKR @ 4011' LD CSG TST T/500 PSI OK MIRU HES TST INS T/7910 PSI RMP 13000 GAL 30# PUREGELL III LT PAD AVG PRESS 3222 PSI AVG R 24 BPM RMP 27000 GAL 15% FERCK SC AICD AVG PRESS 4729 AVG R 39 BPM RMP 8000 GAL TREATED WIR AVG PRESS 5140 AVG R 39 BPM SD ISIP 1107 5 MIN SI 859 10 MIN 749 15 MIN 563 PSI AVG R 40 BPM AVG PRESS 4935 PSI MAX R 42 MAX
(CONTINUED ON BACK)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE SUPV., REGULATION/PRORATIONWW DATE 7/15/02
Type or print name L.M. SANDERS Telephone No. 915/368-1488

(This space for State use)

APPROVED BY [Signature] TITLE ORIGINAL SIGNED BY DATE JUL 18 2002
Conditions of approval, if any:

EVAC #0524-036

05/17/02 CONTINUED

05/18/02 PRESS 5945 PSI RDMO HES OPEN UP T/FAC TK REL PKR POOH W/34 STDS SECURE SD
POOH LD 3-1/2 PH6 TBG PKR & JET SUBS TIH W/34 STDS POOH LD 3-1/2 PH6 TBG TIH W/BP PERFD SUB & 2-7/8 TBG
RU SWAB EQMT SD

05/19/02 SWAB START FL 3000' 24 SWAB RUNS REC 138 BBL FL W/TR OIL END FL 3000' SD

05/20/02 CREW OFF

05/21/02 KILL WELL POOH W/TBG PERFD SUB & BP WO 4" POORBOY GAS ANCHOR TIH W/TBG & TAC ND BOP NU WH TIH
W/PMP & RODS LD/TST HANG ON CLN LOC RDMO WSU WELL ON TEST - TEMP DROP F/REPORT

07/13/02 6/30 REC 144 BO 128 BW 50 MCF GAS 37% CO2
7/02 130 BO 111 BW 59 MCF GAS 35% CO2
7/04 130 BO 114 BW 62 MCF GAS 37% CO2
WELL PMPG W/LUFKIN C456D-305-144 STRK LENGTH 144" SPM 7.8 2" INSERT PMP 136 JTS 2-7/8 J55 8RD TBG 7 X
2-7/8 TAC SET @ 4167' PMP SET @ 4321' EOT @ 4352' 300' 1" D90 RODS 1925' 7/8 D90 RODS 2050' 3/4" D90 RODS
OIL GRAY 39 FL @ 448' ABOVE PMP WELL ON PRODUCTION - COMPLETE DROP F/REPORT