

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-025-03060

5. Indicate Type of Lease
STATE FEE

6. State Oil & Gas Lease No.
B-1502

7. Lease Name or Unit Agreement Name
EAST VACUUM GB/SA
UNIT #0524

8. Well No.
045

9. Pool name or Wildcat
VACUUM GRAYBURG/SAN ANDRES

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL GAS WELL OTHER

2. Name of Operator
Phillips Petroleum Company

3. Address of Operator
4001 Penbrook Street, Odessa, TX 79762

4. Well Location
Unit Letter F : 1650' Feet From The WEST Line and 1650' Feet From The NORTH Line

Section 5 Township 18S Range 35E NMPM LEA County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3959.4' GL; 3970'RKB

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

- PERFORM REMEDIAL WORK
- TEMPORARILY ABANDON
- PULL OR ALTER CASING
- OTHER:
- PLUG AND ABANDON
- CHANGE PLANS

SUBSEQUENT REPORT OF:

- REMEDIAL WORK
- COMMENCE DRILLING OPNS.
- CASING TEST AND CEMENT JOB
- OTHER: CO T/4600', ACIDIZE, SOQ, CHG RODS & RET
- ALTERING CASING
- PLUG AND ABANDONMENT

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 12/02/96 RU F/RTP, RODS PARTED, STRIPPED OUT OF HOLE,
- 12/03/96 FIN STRIPPING OUT HOLE, START IN HOLE W/SM, IPC SUB, & BLAST JT DROPPED IN HOLE.
- 12/04/96 MI RACK 2-3/8" WS, PU GIH W/SHOE, OVERSHOT, BMPR SUB, JARS, COLLARS & TBG, TAG @ 4455', TRY T/CATCH FISH, COOH W/TOOLS, DIDN'T CATCH FISH, GIH W/OVERSHOT T/BTM CSG, SISD.
- 12/05/96 FIN GIH W/TOOLS, TRY T/CATCH FISH, COOH W/TOOLS, DIDN'T CATCH FISH, LD OVERSHOT, JARS, & BMPR SUB, GIH W/BIT, SET SUB, COLLARS & TBG, JET WASH & CIRC CLN 4315'-4450', PU INTO CSG, SISD.
- 12/06/96 TAG @ 4450' DRL T/4555', JET WASH F/4440'-4555', CIRC CLN, PU INTO CSG, SISD.
- 12/09/96 FIN GIH W/BIT, COULDN'T MK HOLE, COOH W/BIT, GIH W/SHOE, CO UNTIL SHOE PLUGGED, COOH, PIECE OF JUNK IN SHOE, GIH W/SHOE & TBG T/BTM CSG, SISD.

(CONTINUED ON BACK)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature]

TITLE Senior Regulation Analyst DATE 1-9-97

TYPE OR PRINT NAME Larry M. Sanders

TELEPHONE NO. (915) 368-1488

(This space for State Use)

ORIGINAL SIGNED BY TRIM EXATON

APPROVED BY _____ TITLE _____ DATE JAN 15 1997

CONDITIONS OF APPROVAL, IF ANY:

- 12/10/96 FIN GIH W/SHOE, TAG @ 4537', MILL FILL, RETURNS OF BLAST JT, CIRC CLN, COOH W/SHOE, GIH W/OVERSHOT, WK OVERSHOT OVER FISH, COOH, CAUGHT BLAST JT, IPC SUB, & SEAT NIPPLE, GIH W/SHOE & TBG T/BTM CSG, SISD.
- 12/11/96 FIN GIH W/SHOE, TAG @ 4555', DIDN'T MAKE HOLE, COOH W/SHOE, GIH W/BIT, CO F/4555' - 4560', CIRC CLN, COOH LD COLLARS & BIT, SISD.
- 12/12/96 MIRU TBG TSTRS, 1ST IN HOLE W/PKR & TBG, SET PKR @ 4030', LD & TST CSG/TBG ANNUL T/500# OK, SISD.
- 12/13/96 MIRU HES, TST LINES PMP 5000 GALS 15% NEFE HCL ACID, 1500# ROCK SALT IN 1500 GALS X-LINK GELLED BRINE W/BRKR & 35 BBL FR WTR AS FOLLOWS:
1000 GALS ACID, 500# SALT IN 12 BBL X-LINK;
1500 GALS ACID, 500# SALT IN 12 BBL X-LINK;
1500 GALS ACID, 500# SALT IN 12 BBL X-LINK;
1000 GALS ACID, 35 BBL FLUSH, ISIP 1997# 5 MIN 1527# 10 MIN 1255# 15 MIN 1009# MAX PRESS 2980# AVG PRESS 2700# AVG RATE 4.8 BPM, RDMO HES, OPEN UP W/0# ON TBG & FL 900', SWAB BK (STARTER WENT OUT ON RIG), REPAIR STARTER ON UNIT, SWAB BK TOT 36 BBL W/END FL @ 2800', SISD.
- 12/16/96 OPEN UP W/400# ON TBG, FL @ 2800', REC 14 BBL W/END FL @ 3800', SISD.
- 12/17/96 REL PKR, COOH W/TBG, GIH W/OLD TBG, COOH LD, GIH W/COND 2 TBG, ND PAN & BOP, FLNG UP WH, SISD.
- 12/18/96 PROBLEMS STARTING PULLING UNIT DUE T/EXTREME COLD WEATHER, GIH W/PMP & RODS, SPACE OUT, HANG ON, LD & TST PMP ACTION, RDMO DDU, LEAVE PMPG 16 HRS, NO TST.
- 12/19/96 NO TST DUE T/FREEZING WEATHER.
- 12/21/96 PMPNG, NO TST.
- 12/22/96 PMP 24 HRS, TST 5 BOPD 95 BWPD 1 MCF 30.2% CO2.
- 12/23/96 TST 6 BOPD 39 BWPD 1 MCF 22.5% CO2.
- 12/24/96 TST 4 BOPD 41 BWPD 1 MCF 17.2% CO2.
- 12/25/96 TST 5 BOPD 34 BWPD 1 MCF.

COMPLETE DROP F/REPORT