

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.I.		
LAND OFFICE		
OPERATOR		

IL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - I" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	5a. Indicate Type of Lease State ☒ Fed ☐
2. Name of Operator TEXACO Inc. (Well formerly F&A by Marathon)	5. State Oil & Gas Lease No. B-1113
3. Address of Operator P. O. Box 728, Hobbs, New Mexico 88240	7. Unit Agreement Name
4. Location of Well UNIT LETTER K 2310 FEET FROM THE South LINE AND 1650 FEET FROM THE West LINE, SECTION 6 TOWNSHIP 18-S RANGE 35-E NADOM.	8. Form of Lease Name Warn State A/C #2
	9. Well No. 6
	10. Field and Pool, or Whichever Vacuum Grayburg San Andres
15. Elevation (Show whether DF, RT, GR, etc.) 3980' (GR)	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	
		OTHER Re-plug subject P&A Well ☒	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rigged up. Install BOP.
2. Drill out cement plugs & retainer to 805'.
3. Unable to clean out below 805'.
4. Well returned to P&A status 2-29-80 to be monitored by TEXACO Inc.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Asst. Dist. Supt. DATE 3-5-80

APPROVED BY FOR RECORD ONLY TITLE DATE

CONDITIONS OF APPROVAL, IF ANY: