

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-03084
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil / Gas Lease No.	857943
7. Lease Name or Unit Agreement Name	CENTRAL VACUUM UNIT
8. Well No.	110
9. Pool Name or Wildcat	VACUUM GRAYBURG SAN ANDRES
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3975'

SUNDRY NOTICES AND REPORTS ON WELL (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well:	OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator	TEXACO EXPLORATION & PRODUCTION INC.
3. Address of Operator	205 E. Bender, HOBBS, NM 88240
4. Well Location	Unit Letter <u>J</u> : 1980 Feet From The <u>SOUTH</u> Line and <u>2310</u> Feet From The <u>EAST</u> Line Section <u>6</u> Township <u>18S</u> Range <u>35E</u> NMPM <u>LEA</u> COUNTY
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3975'	

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2-25-98: MIRU.
2-27/3-13-98: MILLING WINDOW & DRILLING.
3-14-98: RIG DOWN
3-25-98: SWAB TEST
3-31-98: REL PKR & TOH W/TBG & PKR. TIH W/MOTOR, GAS SEPERATOR, PUMP, SUB, & 2 7/8" TBG.
4-01-98: PUMP @ 12' KB. KILL WELL. NDBOP. NUWH. PUMPED UP.
4-03/4-21-98: PUMPING & TESTING.
4-22-98: REL RBP @ 1850'. CHANGE OUT RAMS. TIH W/3 12" TBG TO 3950'. SET PKR @ 3967'. NU TREE.
4-25-98: FLOWBACK LINE. OPEN WELL. ON VACUUM.
4-26-98: SET RBP @ 3965'.
4-28-98: DUMP BAIL 1 SK SAND ON RBP @ 3965'.
4-29-98: TIH W/PERF SUB & 3 1/2" TBG. PSA 3875'. NU TREE. TEST ANNULAS TO 500#.
5-03-98: ND TREE. REL PKR. TOH W/3 1/2" TBG. CHANGE RAMS. TIH W/RETR TOOL ON 2 7/8" PROD TBG TO 3600'.
5-04-98: CIRC SD OFF RBP. REL RBP. TIH W/PMP, 2 7/8" PROD TBG. NDBOP. NUWH.
5-05-98: TIE INTO BTRY.
5-11-98: ON 24 HR OPT. PUMPED 170 BO, 209 BW, & 62 MCF.
FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant DATE 5/20/98

TYPE OR PRINT NAME J. Denise Leake Telephone No. 397-0405

(This space for State Use) ORIGINAL SIGNED BY CHRIS WILLIAMS
DISTRICT I SUPERVISOR

APPROVED BY Chris Williams TITLE District I Supervisor DATE 5/20/98

CONDITIONS OF APPROVAL, IF ANY: