

Submit 3 Copies To Appropriate District Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

811 South First, Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

WELL API NO.

30-025-03086

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

B-1031

7. Lease Name or Unit Agreement Name:

Central Vacuum Unit

8. Well No.

217

9. Pool name or Wildcat

Vacuum Grayburg-SA

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

Texaco Exploration & Production, Inc.

3. Address of Operator

P. O. Box 3109, Midland, TX 79702

4. Well Location

Unit Letter O : 660 feet from the South line and 1980 feet from the East line

Section 6

Township 18S Range 35E NMPM Lea County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

1. Unable to latch on to RBP @ 4450' spot 40 Sx plug 4450'-4285' Tag @ 4261' (Grayburg-San Andres)
2. Spot 40 Sx plug 3906'-3700' (Queen)
3. Perf 6 holes @ 2800' Sqz w/75 Sx 2800'-2500' (Yates-B-Salt) Tag @ 2418'
4. Unable to Sqz spot 75 Sx plug 1700'-1400' (T-Salt) Tag @ 1372'
5. Perf 6 holes @ 400' Sqz 125 Sx plug 400'-200' (10 3/4" shoe) Tag @ 151'
6. Circ cmt 30' to Surf w/15 Sx, Install dry hole marker. 10/02/01

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE MANAGER

DATE 10/02/01

Type or print name

JIMMY BAGLEY

Telephone No. 915 683-4996

(This space for State use)

APPROVED BY

Billy E. ...

TITLE

DATE

Conditions of approval, if any:

GWW