

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
310 Old Santa Fe Trail, Room 206
Santa Fe, New Mexico 87503

WELL API NO.	03092 30-025-30920
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	E-6002
7. Lease Name or Unit Agreement Name	B. Lee State
8. Well No.	#1
9. Pool name or Wildcat	Vacuum Abo Reef

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator Lynx Petroleum Consultants, Inc.	
3. Address of Operator P.O. Box 1708, Hobbs, NM 88241	
4. Well Location Unit Letter <u>F</u> : <u>1650</u> Feet From The <u>North</u> Line and <u>2236</u> Feet From The <u>West</u> Line Section <u>7</u> Township <u>18S</u> Range <u>35E</u> NMPM <u>Lea</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) <u>3966' GR</u>	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input checked="" type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Set a C.I.B.P. at 8150'.
2. Circulate the hole with Packer Fluid.
3. Pressure test casing to 500 psig for 30 minutes.
4. Review for possible recompletion at a later date.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Marc Wise Marc Wise TITLE President DATE 6/13/00

TYPE OR PRINT NAME Marc Wise TELEPHONE NO. 505-392-6950

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

PROPOSED TEMPORARY ABANDONMENT
6/13/00

Elev. 3966' GR +14' KB

T.O.C. @ 270' (Temp. Sur.)

342' - 13 3/8", 48#, H-40 Casing
Cemented w/275 sxs. Circulated to Surf.

3370' - 8 5/8", 24# & 32#, J-55 Casing.
Cemented w/1150 sxs.

PACKER
FLUID

T.O.C. @ 4060' (Temp. Sur.)

SET A C.I.B.P. AT 8150'

Perfs 8206'-8385'

Perfs 8405'-8628'

8859' - 5 1/2", 15.5# & 17# Csg
Cemented w/650 sxs

T.D. @ 8859'

LYNX PETROLEUM
B. Lee State #1
1650' FNL & 2236' FWL
Sec. 7, T-18S, R-35E
Lea County, N.M.