## NEW MEY'CO OIL CONSERVATION COMMISSION

Santa Fe. New Mexico

(Form C-104) Revised 7/1/57

Vev

REQUEST FOR (OIL) - (CAR) ALLOWABLE

This form shall be submitted by the operator before an initial allowable will be assigned to any completed Oil or Gas well. Form C-104 is to be submitted in QUADRUPLICATE to the same District Office to which Form C-101 was sent. The allowable will be assigned effective 7:00 A.M. on date of completion or recompletion, provided this form is filed during calendar able will be assigned effective 7:00 A.M. on date of completion or recompletion, provided this form is filed during calendar month of completion or recompletion. The completion date shall be that date in the case of an oil well when new oil is delivmonth of completion for recompletion of 15.025 psia at 60° Fahrenheit.

E ARE HEREBY REQUESTIN Skelly Oil Company (Company or Operator) *D* Sec.				т <b>18-5</b>	(Lease) R <b>35-E</b>	<u>NMPM.</u> ,	Vacuum Abe	)	Pool
	Latter	, Sec		•• • • • • • • • • • • • • • • • • • •	,	10 1061	Data Del 111	ng Gemulated	Nov. 10, 1963
L	88.	. <b></b>		County. Date	Spudded W	, Total	Depth 9050	PBTI	Nov. 10, 1961
P	lease inc	dicate lo	cation:	Tor Cil/Gas Fe	8726'	Name	of Prod. Form.	Abe	
D	C	B	A	PRODUCING_INT					
1				Perforations	8824' -	88741		Depth	
E	F	G	Ħ	Open Hole		Depth Casir	g Shoe 904	Tubin	
	Sec.	8		OIL WELL TEST	-				Choke
L	K	† J	I	Netural Prode	. Testi	_bbls.oil,	bbls wat	er inhr	s,min. Size
							second of	uniume of oil	equal to volume of
M	N	10	P	load oil used	d): 320 bb	ls.oil, <u>0</u>	bbls water i	n <b>16</b> hrs,	min. Size 3/4
				GAS WELL TEST	<u>r</u> –				
301	PHL &	3581	FWL	Natural Prod	- . Test:	MCF/	Day; Hours flow	edCho	oke Size
			enting Reco	and wathod of Te	sting (pitot. k	ack pressure, e	tc.):		
	, Gasing	Feet		Test After A	cid or Fracture	• Treatment:	and the state of the	MCF/Day; Ho	urs flowed
	e	et At		Choke Size_	Method	of Testing:	· · · · · · · · · · · · · · · · · · ·		
									id, water, oil, and
13-2	3/8"	305'	305	Acid or Frac	ture Treatment	(Give amounts C	f materials use	ed, such as ac	
	3/8*	305'	1	Acid or Fractions and): Acid Casing	ture Treatment lised with Tubing 7	(Give amounts c 4000 gals. Date fire	f materials use <b>acid.</b> it new o tanks <b>Dece</b>	ed, such as ac	id, water, oil, and
	3/8"		305 1100	Acid or Fractions and): Acid Casing	ture Treatment lised with Tubing 7	(Give amounts c 4000 gals. Date fire	f materials use <b>acid.</b> it new o tanks <b>Dece</b>	ed, such as ac	
8-	3/8# 5/8#	305'	1	Acid or Frac sand): Acid Casing Press. Gil Transpor	ture Treatment dised with Tubing Press. 7: ter Texas-	(Give amounts C	f materials use <b>acid.</b> it new o tanks <b>Dece</b>	ed, such as ac	
8- 5-	3/8" 5/8" 1/2"	305' 3254' 9049'	1100 925	Acid or Fract sand): Acid Casing Press. Gil Transpor Gas Transpor	ture Treatment dised with Tubing Press. 7 ter Texas-l None	(Give amounts of 4000 gals. Date firs oil run f	f materials use acid. t new to tarks Deco Pipe Line (	ed, such as ac mber 12, S Company	1961
8- 5-	3/8" 5/8" 1/2"	305' 3254' 9049'	1100 925	Acid or Fract sand): Acid Casing Press. Gil Transpor Gas Transpor	ture Treatment dised with Tubing Press. 7 ter Texas-l None	(Give amounts of 4000 gals. Date firs oil run f	f materials use acid. t new to tarks Deco Pipe Line (	ed, such as ac mber 12, S Company	1961
8- 5- 2* Remai	3/8" 5/8" 1/2" rks:	305' 3254' 9049' 8010' 011 flo	1100 925	Acid or Fract sand): Acid Casing Press. Gil Transpor Gas Transpor	ture Treatment dised with Tubing Press. 7: rter Texas-l rter None in 16 hour	(Give amounts of A000 gals. Date firs oil run f New Mexico	f materials use acid. t new o tariks Dece Pipe Line ( 3/4" choke	mber 12, " Company T. P. 75	1961
8- 5- 2" Remai	3/8" 5/8" 1/2" rks:	305' 3254' 9049' 8010' 011 flo	1100 925	Acid or Fract sand): Acid Casing Press. Gil Transpor Gas Transpor	ture Treatment dised with Tubing Press. 7: rter Texas-l rter None in 16 hour	(Give amounts of A000 gals. Date fire oil run file iew Mexico	f materials use acid. t new to tarks Deco Pipe Line ( 3/4" choke to the best of I	t. P. 75	1961
8- 5- 2" Remai	3/8" 5/8" 1/2" rks: We	305' 3254' 9049' 9049' 911 flo	1100 925 	Acid or Fract sand): Acid Casing Press. Gil Transpor Gas Transpor	ture Treatment dised with Tubing Press. 72 ter Texas-l rter None in 16 hour above is true	(Give amounts of 4000 gals. Date firs oil run first inv Mexico , through and complete Ske	f materials use acid. it new to tariks Dece Pipe Line ( 3/4" choke to the best of r 11y 011 Co	nd, such as action of the second seco	1961
8- 5- 2" Remai	3/8" 5/8" 1/2" rks: We hereby	305' 3254' 9049' 9049' 911 flo certify 1	1100 925 	Acid or Fract sand): Acid Casing Press. Gil Transpor Gas Transpor Dbls. Oil S	ture Treatment dised with Tubing Press. 7: rter Texas-l rter None in 16 hour above is true 	(Give amounts of 4000 gals. Date firs oil run first inv Mexico , through and complete Ske	f materials use acid. it new to tariks Deco Pipe Line ( 3/4" choke 3/4" choke to the best of r 11y Oil Compa (Compa h. E.	T. P. 75 ny knowledge ny or Operator	1961
8- 5- 2" Remai	3/8" 5/8" 1/2" rks: We hereby	305' 3254' 9049' 9049' 911 flo certify 1	1100 925 owed 320 that the in	Acid or Fractor sand): Acid Casing Press. Gil Transpor Gas Transpor Dobls. Oil State of ormation given	ture Treatment dised with Tubing Press. 7: rter Texas-l none in 16 hour above is true 19	(Give amounts of 4000 gals. Date firs oil run f inv Mexico , through and complete Ske By:	f materials use acid. it new to tariks Dece Pipe Line ( 3/4" choke 3/4" choke to the best of r 11y Oil Compa NED h. E.	nd, such as action of the second seco	1961
8- 5- 2* Remai	3/8" 5/8" 1/2" rks: We hereby	305' 3254' 9049' 9049' 911 flo certify 1	1100 925 owed 320 that the in	Acid or Fractor sand): Acid Casing Press. Gil Transpor Gas Transpor Dobls. Oil State of ormation given	ture Treatment dised with Tubing Press. 7: rter Texas-l none in 16 hour above is true 19	(Give amounts of 4000 gals. Date firs oil run first inv Mexico through and complete Ske By:	f materials use acid. it new to tariks Dece Pipe Line ( 3/4" choke 3/4" choke 3/4" choke 11y 011 Co (Compa NED) H. E.	ny or Operator	1961 <i>t</i> .
8- 5- 2- Remai	3/8" 5/8" 1/2" rks: We hereby	305' 3254' 9049' 9049' 911 flo certify 1	1100 925 owed 320 that the in ERVATIO	Acid or Fractor sand): Acid Casing Press. Gil Transpor Gas Transpor Dbls. oil : oformation given	ture Treatment dised with Tubing Press. 7: rter Texas-l rter None in 16 hour a above is true 	(Give amounts of 4000 gals. Date fire oil run fire Mexico fire , through and complete Ske By: Title. Se	f materials use acid. t new to tarks Dece Pipe Line ( 3/4" choke 3/4" choke 3/4" choke to the best of r 11y 011 Co (Compa NED) H. C. () t. Supt. end Communic	T. P. 75 mber 12, 2 Company T. P. 75 ny knowledge mpany ny or Operator Signatur Signatur	1961 * .
8- 5- 2" Remain I Appro	3/8" 5/8" 1/2" rks: We hereby	305' 3254' 9049' 8010' 011 210 certify 1 CONSI	1100 925 owed 320 that the in ERVATIO	Acid or Fractor sand): Acid Casing Press. Gil Transpor Gas Transpor Dobls. Oil State of ormation given	ture Treatment dised with Tubing Press. 7: rter Texas-l rter None in 16 hour a above is true 	(Give amounts of 4000 gals. Date firs oil run f iew Mexico through and complete Ske By: Title. Ske Ske Ske	f materials use acid. t new t new to tarks Deca Pipe Idne ( 3/4" choke 3/4" choke 3/4" choke 3/4" choke to the best of r 11y Oil Co t. Supt. and Communic bily Oil Co	T. P. 75 mber 12, Company T. P. 75 my knowledge mpany Signatur Signatur ations regarding mpany	1961 * .