## ATTACHMENT - FORM C-103 STATE SECTION 27 SWDS - WELL #2 30-025-03142

08-20-98	FIN RIH W/ OVERSHOT W/ GRAPPLE ON DP, LATCH ON FISH @2695' (FISH DROPPED 1827'), PULL 130,000# AND FISH PARTED, POH REC 1 JT TBG LEFT COLLAR LOOKING UP, TOP FISH NOW @2734', RESTRING NEW TBG LINE SWIFN.
08-21-98	RIH W/ OVERSHOT W/ GRAPPLE ON DP, LATCH ON FISH @2734', PULL 110,000# FISH HELD TOGETHER, KEY WL RAN FREEPOINT AND FOUND CSG FREE AT 5000', RAN STRING SHOT AND BACK OFF 4 ½" CSG @4993', POH W/ DP LAID DOWN OVERSHOT LEFT 4 CSG SETTING ON SLIPS. CHANGE RAMS TO 4 ½", SWIFN.
08-22-98	FIN POH LAID DOWN DUOLINED TBG, HAD LARGE AMOUNT OF CORROSION AND PITS ON OUTSIDE OF TBG, LINING LOOKED GOOD, RIH W/ OVERSHOT W/ GRAPPLE, LATCH ON FISH @4993', PULL 120,000# FISH HELD TOGETHER, KEY WL RAN FREEPOINT STOPPED IN TOP FISH @4993', UNABLE TO WORK PAST TOP FISH, SWIFN.
08-23-98	KEY WL CO. RIH W/ SPUD BARS, JARS, SPUD THRU TOP FISH @9994', POH, RIH W/ FREEPOINT TOOL AND FOUND TBG FREE @10,000', POH, RIH W/ STRING SHOT AND BACK OFF TBG @9994', POH LAID DOWN DUOLINED TBG, HAD HEAVY CORROSION AND PITTING ON OUTSIDE OF TBG. SWIFN.
08-24-98	RIH W/ OVERSHOT W/ GRAPPLE DP TO 3900', LATCH ON FISH @9994', WORK FISH TO 180,000# W/ NO MOVEMENT, SWIFN.
08-25-98	KEY WL CO RIH W/ FREEPOINT TOOL AND STOP @12,702' UNABLE TO WORK DOWN HOLE, POH, RIH W/ SPUD BARS, JARS, SPUD @12,702', UNABLE TO WORK DOWN, POH, WORK STUCK TBG, ATTEMPT TO TORQUE FISH, WORK FISH FM 160,000 TO 180,000 MADE FEET AND STOP, RIH W/ SPLIT SHOT ON WL TO 12,650' ATTEMPT TO SPLIT COLLAR @12,650'. POH W/ CCL AND STOP IN THE OVERSHOT @9994', ATTEMPT TO WORK WL TOOLS, STUCK TOOLS IN THE OVERSHOT ATTEMPT TO PULL OUT OF THE ROPE SOCKET, PULLING UP TO 4600#, SWIFN.
08-26-98	JARREL SVCS DROP KINLEY WL CUTTER AND CUT KEY WL @9994', WORK FISH FM
08-27-98	WORK STUCK TBG FM 140,000-200,000#, CAME FREE W/ 50,000# DRAG PUH 254' AND STOP, KEY WL RAN FREEPOINT TBG FREE @12,352', RAN STRING SHOT ATTEMPT TO BACK OF TBG @12,352' BROKE @11,120', POH W/ 254 JTS 23.875" DP, SWIFN.
08-28-98	FIN POH LAID DOWN 28 JTS 4 ½" TBG, RIH W/ 6 1/8" OVERSHOT, BS, JARS, 6 DCS ACC
08-29-98	FIN RIH W/ OVERSHOT, LATCH ON FISH @10,837', WEDGE WL RAN FREEPOINT, FREE @ 12,354', UNABLE TO TORQUE FISH @11,860', RIH W/ ROLL SHOT AND PARTED TBG @12,354', WORK STUCK TBG UP HOLE 185', RIG DOWN FOR SHEAVE REPAIRS, SWIFN.
08-30-98	WORK STUCK FISH, JAR ON FISH, CAME FREE, POH LAID DOWN 39 JTS 4 ½" TBG REC 277 JTS 4 ½" DUOLINED TBG, LEFT 17 JTS 4 ½" TBG IN HOLE SWIFN.
08-31-98	RIH W/ 6 1/8" FLAT BTM MILL, BS, JARS, 6 4 1/4" DCS ON 2.875" DP, TAG TOP @12,180', JAR DOWN ON FISH FOR 1 HR UNABLE TO MOVE FISH, POH W/ 144 JTS 2.875" DP, SWIFN.
09-01-98	POH W/ 2.875" DP & BHA, RU HOWCO WL, RAN ELECTRO MAGNETIC CSG INSPECTION LOG & GAMMA RAY, FROM 11,988' TO 50', FOUND POSSIBLE HOLES 10,514', 10,363', 9,053', 8,754', ALSO 9 5/8" CSG ABOVE LINER TOP HAD BAD SPOT, RD HOWCO, SWI SDFN.
09-02-98 09-03-98	7" RBP & PKR, PKR @ 11,851', RBP @ 11,858'. PRES CSG 320# RAN 30 MIN SIMULATED H-5, UNSET RBP, POH LD DP, PKR & RBP, SWI
0, 0, 1	SDFN, WEEKEND & WAIT ON INJ EQUIP.