

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. L-1568
7. Unit Agreement Name
8. Farm or Lease Name State Q
9. Well No. 1
10. Field and Pool, or Wildcat Ark. Jct. - Queen
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-
2. Name of Operator AZTEC OIL & GAS COMPANY
3. Address of Operator P. O. Box 837, Hobbs, New Mexico 88240
4. Location of Well UNIT LETTER G 1980 FEET FROM THE North LINE AND 1980 FEET FROM THE East LINE, SECTION 12 TOWNSHIP 18-S RANGE 36-E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 3785 DF

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well was Plugged and Abandoned as follows:

1. Tagged bottom with 2-3/8" tubing at 4560'. Spotted 25 sxs cement plug 4560-4222'. Circulated hole with Mud Laden Fluid.
2. Spotted 25sxs. cement plug from 3147-2809'.
3. Cut casing at 2021' and pulled out of hole.
4. Ran tubing to 2057' and spotted 25 sxs plug.
5. Spotted 25 sxs plug 50' below casing shoe at 306'.
6. Spotted 10 sxs cement plug in top of surface.
7. Installed Dry Hole Marker and leveled location.

Work Complete 1-28-73

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>original signed by LESTER L. DUKE</u>	TITLE <u>District Superintendent</u>	DATE <u>June 11, 1973</u>
APPROVED BY <u>John W. Runyan</u>	TITLE <u></u>	DATE <u></u>

CONDITIONS OF APPROVAL, IF ANY: