		1	····		
NO. OF C	OPIES RECEIVED			Form C-103	
DIST	DISTRIBUTION			Supersedes Old	
SANTA FE NEW MEXICO OIL CONSERVATION COMMISSION			C-102 and C-103 Effective 1-1-65		
FILE					
		-		5a. Indicate Type of Lease	
U.S.G.S.		4	•	State Fee X	
LAND O	+	-		5. State Oil & Gas Lease No.	
OPERAT	OR				
				***************************************	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.					
USE "APPLICATION FOR PERMIT " (FORM C-101) FOR SUCH PROPOSALS.)				7. Unit Agreement Name	
1. 01L	GAS [			7. Onit Agreement Name	
WELL OTHER-					
2. Nanie of Operator				8. Farm or Lease Name	
Shell Oil Company				Rice	
3. Address of Operator				9. Well No.	
P. O. Box 1509, Midland, Texas 79701				2	
4. Location of Well				10. Field and Pool, or Wildcat	
UNIT LETTER 0 660 FEET FROM THE South LINE AND 1980 FEET FROM				Hobbs (G-SA)	
UNIT	LETTER ,	FLET FROM THE	LINE AND JYOU FEET FROM		
	East	13 TOWNSHIP 185	275	ΔΗΠΗΠΗΠΗΠΗ	
THE _	LASL LINE, SEC	TION TOWNSHIP	RANGE J/E NMPM.	XIIIIIIIIIIIIIIIIIIIIIII	
mm	mmmm	15. Elevation (Show whether	DF. RT. GR. etc.)	12. County	
			78 DF	Lea	
İΠΠ					
16.	Check	Appropriate Box To Indicate N	Nature of Notice, Report or Ot	her Data	
	NOTICE OF	INTENTION TO:	SUBSEQUEN	T REPORT OF:	
	,				
PERFORM	REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING	
TEMPORAR			COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT	
		CHANGE PLANS	CASING TEST AND CEMENT JOB		
			OTHER		
OTHER					
UTALN.					
		Operations (Clearly state all pertinent det	ails, and give pertinent dates, including	estimated date of starting any proposed	
work)	SEE RULE 1103,	8-15-73 to	8-26-73		
		0 19 73 60	0-20-75		
1	Perforated 5"	liner at 4072 4073 4074	1088 1089 1090 (6 h	log) with 1 TODE	
<b>.</b>	1. Perforated 5" liner at 4072, 4073, 4074, 4088, 4089, 4090 (6 holes) with 1 JSPF.				
2	2 Apidizod $(0.72)$ $(0.00)$ with 1000 and 15% and 1				
2. Acidized 4072 - 4090 with 1000 gal 15% acid.					
3. Pumped 100 sx Class H cement, obtained squeeze with 43 sx cement in perforations					
	4072 - 4090.				
4.	4. Perforated 5" liner at 4116, 4127, 4136, 4140, 4148 (5 holes) with 1 JSPF.				
5.	5. Acidized 4116 - 4148 with 1000 gal 15% NEA.				
6. Set Model K cement retainer at 4068'. Pumped 50 sx Class H cement. Obtained squeeze					
••	with 20 sx cement into perforations 4116 - 4148, Left 5 sx cement from bottom of				
	retainer to per		0 = 4140, Let $U$ Sx cen		
	recarner to per	. TOT & LTUIS .			
7. Perforated 5" liner at 3967, 3986, 3997, 4008, 4015, 4024, 4050, 4055, 4058					
/•		TODE	, 4008, 4015, 4024, 4050	1, 4055, 4058	
	(9 holes) with 2	JDFF.		(cont. on back)	
	w antify that the information	on above is true and complete to the best	of my knowledge and helief.		
is, i hereb	y certify that the information				
/	it a		. E. Cordray		
ISNED (	16.On	dial TITLE S	taff Engineer	10-9-73	
		J		0.0.5	
	C	rig. Signed by		UCT 1 2 1170	
		oe D. Ramey		DATE	
APPHUVED B		Quat. I, Supy.			
CONDITIO	INS OF APPROVAL, IF AN	Y: -,			

- 8. Acidized perforations 3967 4058 with 1500 gal 15% NEA.
- 9. Set BP at 4035'. Ran 129 jts. 2 1/2" tubing, hung at 4024'. Ran 2 1/2" X 2" X 4" RWBC pump on 94 - 3/4" and 63 - 7/8" rods. Placed on production.