

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name

N. HOBBS (G/SA) UNIT
SECTION 23

1. Type of Well:

OIL
WELL ☒

GAS
WELL ☐

OTHER

2. Name of Operator

Shell Western E&P Inc.

8. Well No.

311

3. Address of Operator

P.O. Box 576 Houston, TX 77001-0576

9. Pool name or Wildcat

HOBBS (G/SA)

4. Well Location

Unit Letter B : 330 Feet From The NORTH Line and 1650 Feet From The EAST Line

Section 23 Township 18S Range 37E NMPM LEA County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3686' DF

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: TAG/PT (VERIFIED TA'D STATUS) ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8-29 TO 8-30-91:

TAG CMT @ 3880'. PT CSG TO 530#. SI OVERNITE LEAVING PRES ON WELL. NEXT AM:
WELLBORE STILL HOLDING 530#. (CHART ATTACHED) BLED OFF PRES. WELL IS TA'D.

NOTE: PURSUANT TO THE PROVISIONS OF NMOC D RULE 203, SHELL WESTERN HEREBY REQUESTS
TEMPORARY ABANDONMENT STATUS FOR A PERIOD OF UP TO FIVE YEARS.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J.H. Smitherman TITLE REGULATORY SUPV. DATE 9/09/91

TYPE OR PRINT NAME J.H. Smitherman TELEPHONE NO. 713/870-3797


(This space for State Use) ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

This Approval of Temporary
Abandonment Expires 9-1-96

SEP 16 1991



Shell
NH#2
23-3-11

SWEPI-NMPU
HOBBES FIELD, NHWFU
TEST OF INJECTION
MECHANICAL INTEGRITY
WELL NO. 23-317
NMOC HOLE 704
PUMP OPER. SIGNATURE *[Signature]*
OCD REP SIGNATURE *[Signature]*
SWEPI REP SIGNATURE *[Signature]*
DATE 8/29/91

RECEIVED

SEP 09 1991

CCP
HOBBES OFFICE

23-3-11