

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. <u>387-025-125475</u>
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> INJECTOR	7. Lease Name or Unit Agreement Name N. HOBBS (G/SA) UNIT SECTION 23
2. Name of Operator SHELL WESTERN E&P INC.	8. Well No. 341
3. Address of Operator P. O. BOX 576, HOUSTON, TX 77001 (WCK 5237)	9. Pool name or Wildcat HOBBS (G/SA)
4. Well Location Unit Letter <u>0</u> : <u>990</u> Feet From The <u>SOUTH</u> Line and <u>1650</u> Feet From The <u>EAST</u> Line Section <u>23</u> Township <u>18S</u> Range <u>37E</u> NMPM <u>LEA</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3683' DF	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: <input checked="" type="checkbox"/> TA'D

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4-28 to 5-03-94:

POH w/inj eqmt. Set CIBP @ 4060' & capped w/35' cmt. Circ inhib fl. PT csg to 500# for 30 min, held. (Chart attached) Secured well for TA'd status. Well is TA'd.

Pursuant to the provisions of NMOCD Rule 203, Shell Western hereby requests temporary abandonment approval for a period of five years.

This Approval of Temporary
Abandonment Expires 5-1-99

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE A. J. Durrani TITLE TECH. MGR. - ASSET ADMIN. DATE 5/18/94
TYPE OR PRINT NAME A. J. DURRANI (713) 544-3797 TELEPHONE NO.

(This space for State Use)

ORIGINAL SIGNED BY JERRY GEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE MAY 25 1994

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

MAY 23 1994

**JOE HODGES
OFFICE**

