

Ì....

Submit this report in triplicate to the Oil Conservation Commission or its proper agent within ten days after the worm specified is completed. It should be signed and sworn to before a notary public for reports on beginning drilling oper-ations, results of shooting well, results of test of casing shut-off, result of plugging of well, and other important operations, even though the work was witnessed by an agent of the Commission. Reports on minor operations need not be signed and sworn to before a notary public. See additional instructions in the Rules and Regulations of the Commission.

of ------**y\_1**• -•

	indicate na					
EPORT ON BEGINNING	G DRILLING OPER	A-	REPORT ON I	REPAIRING	WELL	
EPORT ON RESULT OF ICAL TREATMENT O	SHOOTING OR CHI F WELL	EM-	REPORT ON ALTERIN	PULLING OF G CASING	R OTHERWI	SE
REPORT ON RESULT OF TEST OF CASING SHUT-OFF			REPORT ON DEEPENING WELL			X
EPORT ON RESULT OF	PLUGGING OF WE	ELL				
	¥or	nument, Ner	r Mexico Place		August 12	2 <b>. 1946</b>
IL CONSERVATION CO ANTA FE, NEW MEXIC entlemen:						
ollowing is a report on the	e work done and the	results obtain	ed under the head	ding noted ab	ove at the	
Amerada Petroleum Company or	Corporation		State E	Well No.	2	in the
	of Sec	24			37E	, N. M. P. M.,
	Field	Lea				
he dates of this work were						
4268' Total Depth J-55. 8 Row	ed plan was ( <b>vener</b> TAILED ACCOUNT , finished 6 <sup>±</sup> nd Thread. Ran	) obtained. ( COF WORK Hole at 8 ge 2. Seam	Cross out incorrec DONE AND RES ;30AM August less Steel Ca	et words.) SULTS OBTA 6, 1946. asing as 1	INED Ran 3264	n Baker Sett
A268: Total Depth J-55, 8 Roun Shoe on both 30 Sax Cempi set 24 hours and set Bake	ed plan was (warned TAILED ACCOUNT , finished 6 <sup>+</sup> / <sub>+</sub> " nd Thread, Rang tom and 5 <sup>+</sup> / <sub>2</sub> " Bai nt, Top of line s and went in 1 or detrievable Pressure Below	b) obtained. ( C OF WORK Hole at 8 ge 2, Seam ker Reg <sup>P</sup> a ar at 3942 hole with Cement Re Retainer	Cross out incorrect DONE AND RES ;30AM August less Steel Ca ttern Casing ' and bottom drill pipe and tainer at 38"	t words.) SULTS OBTA 6, 1946. asing as 1 on top in of liner nd drilled 77' (65') ove retain Corp.	INED Ran 3264 iner with werted an at 42684, i out cease above lin mer for 45	n Baker Sett ad cemented . Let cemen ent to 4262! her and test
nd approval of the propose DE 4268: Total Depth J-55, & Hour 30 Sax Cemel set 24 hour and set Bake with 3000# 1 was OK.	ed plan was (worst TAILED ACCOUNT , finished 6 <sup>±</sup> nd Thread, Rang tom and 5 <sup>±</sup> Bai nt, Top of line s and went in 1 or detrievable Pressure Below Furse	b) obtained. ( C OF WORK Hole at 8 ge 2, Seam ker Reg Pa er at 3942 hole with Cement Re Retainer	Cross out incorrect DONE AND RES ;30AM August less Steel Ca ttern Casing ' and bottom drill pipe and tainer at 38 and 1000# Ab Amerada Pet.	t words.) SULTS OBTA 6, 1946. asing as 1 on top in of liner nd drilled 77' (65') ove retain Corp.	INED Ran 3264 iner with werted ar at 42684. i out cease above lin ar for 45 Fo	h Baker Sett ad cemented . Let cemen ent to 4262 her and test 5 Minutes an <u>Dreman</u> Title
A268: Total Depth J-55, 8 Roun Shoe on bot 30 Sax Cemen set 24 hour and set Bake with 3000# 1 was OK.	ed plan was (yapped TAILED ACCOUNT , finished 6‡" nd Thread, Ran tom and 52" Bai nt, Top of line s and went in 1 er detrievable Pressure Below Furse Name	b) obtained. ( C OF WORK Hole at 8 ge 2, Seam ker Reg Pa sr at 3942 hole with Cement Re Retainer	Cross out incorrect DONE AND RES ;30AM August less Steel Ca ttern Casing ' and bottom drill pipe and tainer at 38' and 1000# Ab Amerada Pet. Compan	t words.) SULTS OBTA 6, 1946. asing as 1 on top in of liner nd drilled 77' (65') ove retain Corp.	INED Ran 326 iner with nverted ar at 4268 i out come above line ber for 4 For the information	h Baker Sett ad cemented . Let cemen ent to 4262 her and test 5 Minutes an <u>Dreman</u> Title
A268: Total Depth J-55, 8 Roun Shoe on both 30 Sax Cempi set 24 hours and set Bake with 3000# 1 was OK. Vitnessed by D. F.	ed plan was (yapped TAILED ACCOUNT , finished 6‡" nd Thread, Ran tom and 52" Bai nt, Top of line s and went in 1 er detrievable Pressure Below Furse Name	b) obtained. ( C OF WORK Hole at 8 ge 2, Seam ker Reg Pa ar at 3942 hole with Cement Re Retainer . i 1946 1	Cross out incorrect DONE AND RES ;30AM August less Steel Ca ttern Casing ' and bottom drill pipe and tainer at 38' and 1000# Ab Amerada Pet. Compan	t words.) SULTS OBTA 6, 1946. asing as 1 on top in of liner nd drilled 77' (65') ove retain Corp.	INED Ran 326 iner with nverted ar at 4268 i out come above lin mer for 4 For the informat	h Baker Sett ad cemented . Let cemen ent to 4262 her and test 5 Minutes an <u>Dreman</u> Title
A268: Total Depth J-55, 8 Roun Shoe on both 30 Sax Cempi set 24 hours and set Bake with 3000# 1 was OK. Vitnessed by D. F.	ed plan was (yapped TAILED ACCOUNT , finished 6‡" nd Thread, Ran tom and 52" Bai nt, Top of line s and went in 1 er detrievable Pressure Below Furse Name	b) obtained. ( C OF WORK Hole at 8 ge 2, Seam ker Reg Pa ar at 3942 hole with Cement Re Retainer . i 1946 1 1	Cross out incorrect DONE AND RES ;30AM August less Steel Ca ttern Casing ' and bottom drill pipe and tainer at 38' and 1000# Ab Amerada Pet. Compan hereby swear or s true and correct Name Position	t words.) SULTS OBTA 6, 1946. asing as 1 on top in of liner nd drilled 77' (65') ove retain Corp.	INED Ran 3264 iner with rverted ar at 42684 i out cean above lin ber for 45 For the informat	h Baker Sett ad cemented . Let cemen ent to 4262 her and test 5 Minutes an <u>Dreman</u> Title
A268: Total Depth J-55, 8 Roun Shoe on both 30 Sax Cempi set 24 hours and set Bake with 3000# 1 was OK. Vitnessed by D. F.	ed plan was (manual TAILED ACCOUNT , finished 6 <sup>±</sup> nd Thread, Rang tom and 5 <sup>±</sup> maint, Top of line s and went in h er detrievable Pressure Below Furse Name afore me this 12	b) obtained. ( C OF WORK Hole at 8 ge 2, Seam ker Reg Pa ar at 3942 hole with Cement Re Retainer . i 19 19 Public 1	Cross out incorrect DONE AND RES ;30AM August less Steel Ca ttern Casing ' and bottom drill pipe and tainer at 38' and 1000# Ab Amerada Pet. Compan hereby swear or s true and correct Name Position	t words.) SULTS OBTA 6, 1946. asing as 1 on top in of liner nd drilled 77' (65') ove retain Corp. y affirm that Boss merace Pet Company or	INED Ran 3264 iner with nverted ar at 4268 i out come above lin mer for 45 For the information for 45 For the information for 45 For the information for 45 For the information for 45 For 45 F	h Baker Sett ad cemented . Let cemen ent to 4262 her and test 5 Minutes an <u>Dreman</u> Title ion given above
A268: Total Depth J-55, 8 Round Shoe on both 30 Sax Cemend and set Bake with 3000# 1 was OK. Vitnessed by D F Subscribed and sworn both day of U_JUL Thanks Jun	ed plan was (monet TAILED ACCOUNT , finished 6 <sup>±</sup> nd Thread, Rang tom and 5 <sup>±</sup> Bai nt, Top of line s and went in 1 er detrievable Pressure Below Furse Name afore me this 12 Notary F	b) obtained. ( C OF WORK Hole at 8 ge 2, Seam ker Reg Pa ar at 3942 hole with Cement Re Retainer . i 19 19 Public 1	Cross out incorrect DONE AND RES 30AM August less Steel Ca ttern Casing and bottom drill pipe ai tainer at 38 and 1000# Ab Amerada Pet. Compan hereby swear or s true and correct Name PositionA	t words.) SULTS OBTA 6, 1946. asing as 1 on top in of liner nd drilled 77' (65') ove retain Corp. y affirm that Boss merace Pet Company or	INED Ran 3264 iner with nverted ar at 4268 i out come above lin mer for 45 For the information for 45 For the information for 45 For the information for 45 For the information for 45 For 45 F	h Baker Sett ad cemented . Let cemen ent to 4262 her and test 5 Minutes an <u>Dreman</u> Title ion given above
A268: Total Depth J-55, 8 Roun Shoe on bot 30 Sax Cemel set 24 hour and set Bak with 3000# 1 was OK. Vitnessed by Subscribed and sworn be day ofAug My commission expires Remarks: APPRO	ed plan was (monet TAILED ACCOUNT , finished 6 <sup>±</sup> nd Thread, Rang tom and 5 <sup>±</sup> Bai nt, Top of line s and went in 1 er detrievable Pressure Below Furse Name afore me this 12 Notary F	b) obtained. ( C OF WORK Hole at 8 ge 2, Seam ker Reg Pa ar at 3942 hole with Cement Re Retainer . i 19 19 Public 1	Cross out incorrect DONE AND RES 30AM August less Steel Ca ttern Casing and bottom drill pipe ai tainer at 38 and 1000# Ab Amerada Pet. Compan hereby swear or s true and correct Name PositionA	t words.) SULTS OBTA 6, 1946. asing as 1 on top in of liner nd drilled 77' (65') ove retain Corp. y affirm that Boss merace Pet Company or	INED Ran 3264 iner with nverted ar at 4268 i out come above lin mer for 45 For the information for 45 For the information for 45 For the information for 45 For the information for 45 For 45 F	h Baker Sett ad cemented . Let cemen ent to 4262 her and test 5 Minutes an <u>Dreman</u> Title ion given above

İ

76 g\*\* and the second 
. general de la des

and a second 
. . . . . .

and the second 