

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name N. HOBBS (G/SA) UNIT SECTION 24
8. Well No. 422
9. Pool name or Wildcat HOBBS (G/SA)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐	2. Name of Operator SHELL WESTERN E&P INC.
3. Address of Operator P. O. BOX 576, HOUSTON, TX 77001 (WCK 4435)	4. Well Location Unit Letter H : 2310 Feet From The NORTH Line and 330 Feet From The EAST Line Section 24 Township 18S Range 37E NMPM LEA County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3671' DF	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ☐ TEMPORARILY ABANDON ☐ PULL OR ALTER CASING ☐ OTHER: <u>Sqz cmt behind lnr, OAP & Act 2</u> ☒	SUBSEQUENT REPORT OF: REMEDIAL WORK ☐ COMMENCE DRILLING OPNS. ☐ CASING TEST AND CEMENT JOB ☐ OTHER: ☐ ALTERING CASING ☐ PLUG AND ABANDONMENT ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. POH w/prod equip.
2. CO to 4265' (PBTD).
3. Set CIBP @ 4120'.
4. Spot 200 gals 15% NEFE HCl above CIBP.
5. Perf sqz holes @ 3950' & 4090' (4 JSPF).
6. Set cmt ret @ 3980'.
7. Pmp 30 SX Cls "C" cmt + 2% CaCl₂. Dmp 80' cmt on top of ret. WOC 24 hrs.
8. DD cmt to 3960'. Pres tst sqzd holes @ 3950' to 500#. Cont drlg out CIBP & cmt to 4110'. Pres tst sqzd holes @ 4090' to 500#.
9. Set RBP @ 4085'. Spot 100 gals 15% NEFE HCl above RBP.
10. Perf SA 4048' - 78' (2 JSPF).

(CONT'D ON REVERSE SIDE)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. H. SMITHERMAN TITLE REGULATORY SUPV. DATE 10-24-89
TYPE OR PRINT NAME J. H. SMITHERMAN (713) 870-3797 TELEPHONE NO.

(This space for State Use)

Orig. Signed by
Paul Kautz
Geologist

OCT 27 1989

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

11. Acidz perfs 4048'-78' w/1500 gals 15% NEFE HCl.
12. Rel RBP & POH.
13. KO CIBP @ 4120' & push to btm.
14. Install prod equip & ret to prod.

OCT 21
CC
HILL