

|                        |  |
|------------------------|--|
| NO. OF COPIES RECEIVED |  |
| DISTRIBUTION           |  |
| SANTA FE               |  |
| FILE                   |  |
| U.S.G.E.               |  |
| LAND OFFICE            |  |
| OPERATOR               |  |

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-75

5a. Indicate Type of Lease  
State ☒ Fee ☐  
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO SEEPER OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

CIL WELL ☐ GAS WELL ☐ OTHER- INJECTOR  
Name of Operator  
SHELL WESTERN E&P INC.  
Address of Operator  
P. O. BOX 576, HOUSTON, TEXAS 77001 (WCK 4435)  
Location of Well  
UNIT LETTER B 660 FEET FROM THE NORTH LINE AND 1980 FEET FROM THE EAST LINE, SECTION 24 TOWNSHIP 18-S RANGE 37-E N.M.P.M.

7. Unit Agreement Name  
N. HOBBS (G/SA) UNIT  
8. Farm or Lease Name  
SECTION 24  
9. Well No.  
311  
10. Field and Pool, or Widened  
HOBBS (G/SA)  
11. County  
LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data.  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐  
TEMPORARILY ABANDON ☐  
PULL OR ALTER CASING ☐  
OTHER ☐  
PLUG AND ABANDON ☐  
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:  
REMEDIAL WORK ☐  
COMMENCE DRILLING OPER. ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER PROFILE CORRECTION, PERF'D & ACD ☒  
ALTERING CASING ☐  
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

2-26-87: Pulled inj equip. CO to 4274' (PBTD). Ran csg inspection log from PBTD to 3900'.

2-27-87: Ran base GR/CCL log from 4248' to 3900'. Set CIBP @ 4200'. Set cmt ret @ 4043'. Sqzd San Andres perfs 4132' - 4186' w/100 sx Cls "C" cmt + 2% CaCl<sub>2</sub> + 1.5% Howco suds + 0.75% HC-2 + 300 SCF N<sub>2</sub>/bbl followed by 25 sx Cls "C" cmt + 2% CaCl<sub>2</sub>. WOC 24+ hrs.

3-02 to 3-04-87: Tagged TOC @ 4041'. DO cmt (& cmt ret @ 4043') to 4127'. Pres tstd csg to 500#, held OK. DO cmt to 4157'. Pres tstd sqzd perfs 4136' - 4156' to 500#, held OK. DO cmt to 4198' & fell thru 2', tagged top of CIBP @ 4200'. Pres tstd all sqzd perfs 4132' - 4186' to 500#, held OK. DO CIBP. DO cmt 4205' - 4256'. Tagged PBTD @ 4274'. Pres tstd to 500#, bled to 0 in 5 min. Ran base GR/CCL log from 4274' - 4000'. Perf'd San Andres 4200' - 4256' (2 JSPF, 68 holes).

3-05-87: Acd perfs 4200' - 4256' w/3000 gals 15% HCl + 200# rock salt. Installed inj equip, setting 4-1/2" Guiberson Uni-Pkr VI @ 4054'. Pres tstd csg to 500#, held OK 15 min. Returned well to inj.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

DATE 3-24-87 A. J. FORE TITLE SUPERVISOR REG. & PERMITTING DATE MARCH 24, 1987  
ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT I SUPERVISOR  
APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE MAR 31 1987

RECEIVED  
MAR 30 1997  
U.S. DEPT.  
HOBBS OFFICE