NEW MEXICO STATE LAND OFFICF

OFFICE OF THE STATE GEOL JIST

SANTA FE, NEW MEXICO

MISCELLANEOUS REPORTS ON WELLS

Submit this report in duplicate to the State Geologist or proper Oil and Gas Inspector within ten days after the work specified is completed. It should be signed and sworn to before a notary public for reports on beginning drilling operations, results of shooting well, results of test of water shut-off, result of abandonment of well, and other important operations, even though the work was witnessed by the State Geologist or Oil and Gas Inspector. Reports on minor operations need not be signed and sworn to before a notary public, but such operations should be witnessed by an Oil and Gas inspector if possible.

REPORT ON BEGINNING DRIRLLING OPERATIONS		REPORT ON DEEPENING WELL			
EPORT ON RESULT OF SHOOTING WELL		REPORT ON PULLING OR OTHERWISE ALTERING CASING		VISE	
EPORT ON RESULT OF TEST OF WATER		-	REPORT ON REPAIRING WELL		
SHUT-OFF		Report Of	n plugging back		
REPORT ON RESULT OF ABANDONMENT OF WELL		Ardmore, Okla.		9-23-35	
		Ardmore,		ate	
Ir P. J. Vesely State	Geologist	,		•	
			ad under the head	ing noted a	above at
Santa Fe, N. Mex. Following is a report on the work do he Samedan Oil Corporation, S	ne and the tate "B"	e results obtaine	Well No	0	_in the
he Samedan Oll Corporation;	Lease 5	T 18S	. R 378	.,	. P. M.
M# 4		., 1	Lea	C	ounty.
	11	September 16	1935		
The dates of this work were as 10 Notice of intention to do the work	was was I	not) sumbitted	on Form SG	1	01
Notice of intention to do the work value	roval of	the proposed p	lan was (was not)) obtained,	(Cros
ut incorrect words.) DETAILED ACCOUNT C Total Depth of well 4343. Plug method.	ged back	to 4190 with	32 sacks cemer	nt by Hall	liburto
DETAILED ACCOUNT C	ged back	to 4190 with	32 sacks cemer	nt by Hall	liburto
DETAILED ACCOUNT C	ged back	to 4190 with	32 sacks cemer	nt by Hall	\ \ \
DETAILED ACCOUNT C	ged back	to 4190 with	32 sacks cemer	nt by Hall	Ì
DETAILED ACCOUNT C	ged back	to 4190 with	32 sacks cemer	nt by Hall	\ \ \
Total Depth of well 4343. Plug method. Subscribed and sworn to before	ged back	to 4190 with	swear or affirm to is true and corre	nt by Hall	
Total Depth of well 4343. Plug method. Subscribed and sworn to before	ged back	I hereby given above Name Position.	swear or affirm to is true and corre	that the in	formation
Total Depth of well 4343. Plug method. Subscribed and sworn to before 27th day of Harry HRwel Notar	ged back	I hereby given above Name Position Representing	swear or affirm to is true and corre	that the inect.	formation TION
Total Depth of well 4343. Plug method. Subscribed and sworn to before	ged back	I hereby given above Name Position.	swear or affirm to is true and corre	that the inect.	formatic
Subscribed and sworn to before 27dday of Hary HRwel Notar	ged back	I hereby given above Name Position Representing	swear or affirm to is true and corre	that the inect.	formation TION
Subscribed and sworn to before 27th day of Hary HRwel Notar My Commission expires	ged back	I hereby given above Name Position Representing	swear or affirm to is true and corre	that the interest. L CORPORA	formatic