

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 87210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
Revised March 25, 1999

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO. 30-025-00551	05511
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>	
6. State Oil & Gas Lease No. 10646	
7. Lease Name or Unit Agreement Name: McMillan	
8. Well No. 1	
9. Pool name or Wildcat EUMONT/YATES SR 9N	
4. Well Location Unit Letter N : 660' feet from the SOUTH line and 1980 feet from the WEST line Section 29 Township 18S Range 37E NMPM LEA County	
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3730' DR	

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
Oil Well ☒ Gas Well ☐ Other

2. Name of Operator  
SOUTHWEST ROYALTIES, INC.

3. Address of Operator  
P.O. BOX 11390, MIDLAND, TEXAS 79702

4. Well Location  
Unit Letter N : 660' feet from the SOUTH line and 1980 feet from the WEST line  
Section 29 Township 18S Range 37E NMPM LEA County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)  
3730' DR

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: TEMPORARILY ABANDONED ☒


12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

Tripped out of hole with production equipment. Tripped in hole and set CIBP @ 3648' and capped with 35 sx of cement in 2 runs. Pressured up and pressure test verbally approved by Mr. Gary Wink w/NMOCD. Chart delivered to District 1 office. Copy attached. Well is temporarily abandoned 9/23/02.

This Approval of Temporary Abandonment Expires

10/28/07

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE  TITLE AREA SUPERVISOR DATE 10/16/02

Type or print name C.M. BLOODWORTH, P.E.


Telephone No. 915/686-9927

(This space for State use)

APPROVED BY  
Conditions of approval, if any:

ORIGINAL SIGNED BY  
GARY W. WINK  
OCC FIELD REPRESENTATIVE II/STAFF MANAGER

OCT 28 2002  
DATE



ORIGINAL CHART DELIVERED TO NMOC DISTRICT 1 OFFICE BY AL PERRY.

10/17/02 3 copies to:

NMOCD  
1625 N. French Drive  
Hobbs, NM 88240

cc: Mr. Mark Al, Vicki W & Elaine