MB. OF COPICS RECEIVED	OIL INSERVATION DIVISION	
DISTRIBUTION	P. O. BOX 2088	Form C-1
SANTA FE	SANTA FE, NEW MEXICO 87501	Revised
FILE	2, 112 M M 2 X 1 C O 8 / 3 0 1	
U.S.G.S.		5a. Indicate Type of Lease
LAND OFFICE		State Fe
OPERATOR		5. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL ON TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. OIL GAB WELL OTHER.		7. Unit Agreement Name
Name of Oberator		
Alpha Twenty-One Production Company		B. Farm or Lease Name Mike
P.O. Box 1206, Jal, NM 88252		9. Well No.
Location of Well		10. Field and Pool, or Wildcat

. 1980 FEET FROM THE SOUTH LINE AND 1980

ERFORM REMEDIAL WORK CASING TEST AND CEMENT JOB

37E

Form C-103 Revised 10-1-78

Eumont Queen

12. County

Lea

SUBSEQUENT REPORT OF:

Fee X

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

18-S

3717 DF

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

15. Elevation (Show whether DF, RT, GR, etc.)

We propose to try new zone as follows:

Recompletion - 7-Rivers Test

NOTICE OF INTENTION TO:

- 1.) Rig pulling unit up.
- 2.) Pull and lay down tubing in hole.

LINE, SECTION 32 TOWNSHIP

- 3.) Clear location of Petro-Lewis tubing, unit, & tank.
- 4.) Run 2-3/8" tubing in hole with scraper.
- 5.) Circulate hole with 2% KCL water.
- 6.) Perforate 7-Rivers zone at approximately 3000'.
- 7.) Set RBP below new perfs.
- 8.) Set RTTS above new perfs & below old perfs.
- 9.) Acidize.
- 10.) Test zone for production.
- 11.) If unproductive, test Grayburg.

hereby certify that the information above is true and comp	lete to the best of my knowledge and belief	
"Michael B. Dans	TITLE Drill Superintendent	DATE 11-8-84
OVED OV Elde 11 Clares	OIL & GAS INSPECTOR	NOV 1 3 1984