

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form O-103
Revised 10-1-77

5a. Indicate Type of Lease	
State ☐	Fee ☒
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO CEMENT OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM O-101) FOR SUCH PROPOSALS.)

6. Indicate Type of Well OIL WELL ☒ GAS WELL ☐ OTHER ☐		7. Unit Agreement Name N. HOBBS (G/SA) UNIT
8. Name of Operator SHELL WESTERN E&P INC.		8. Name of Lease Name SECTION 30
9. Address of Operator P. O. BOX 576, HOUSTON, TEXAS 77001 (WCK 4435)		9. Well No. 111
10. Location of Well UNIT LETTER <u>D</u> <u>330</u> FEET FROM THE <u>NORTH</u> LINE AND <u>330</u> FEET FROM THE <u>WEST</u> LINE, SECTION <u>30</u> TOWNSHIP <u>18-S</u> RANGE <u>38-E</u> N.M.P.M.		10. Field and Pool, or Window HOBBS (G/SA)
11. Elevation (Show whether DF, RT, GR, etc.) 3650' GR		11. County LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPER. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER <u>WSO, DPN, OAP & ACDZ</u> ☒	CASING TEST AND CEMENT JOB ☐	OTHER ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. POH w/prod equip.
2. CO to PBTD (4200').
3. Set CICR @ 4110'.
4. Sqz perfs 4120'-68' w/125 sx Cls "C" cmt + 2% CaCl₂ + 1.5% Howco suds + 0.75% HC-2 + 200 SCF N₂/bbl followed by 25 sx Cls "C" cmt + 2% CaCl₂. WOC 24 hrs.
5. DO CICR + cmt to 4200'. Pres tst sqz to 500#.
6. Dpn well to 4256'.
7. Perf San Andres 4154' - 4227' (2 JSPF).
8. CO to FS @ 4229'.
9. Acdz perfs 4154' - 4227' + OH 4229'-56' w/4000 gals 15% HCl-NEA + 2000# rock salt.
10. Install prod equip & return well to prod.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

FILED A. J. FORE TITLE SUPERVISOR REG. & PERMITTING DATE 3-10-88
APPROVED BY ORIGINAL SIGNED BY JERRY SEXTON TITLE DISTRICT 1 SUPERVISOR DATE MAR 14 1988