

## NEW MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

## MISCELLANEOUS REPORTS ON WELLS

Submit this report in TRIPLICATE to the District Office, Oil Conservation Commission, within 10 days after the work specified is completed. It should be signed and filed as a report on Beginning Drilling Operations, Results of test of casing shut-off, result of plugging of well, result of well repair, and other important operations, even though the work was witnessed by an agent of the Commission. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Report by Checking Below

|                                         |  |                                             |  |                          |          |
|-----------------------------------------|--|---------------------------------------------|--|--------------------------|----------|
| REPORT ON BEGINNING DRILLING OPERATIONS |  | REPORT ON RESULT OF TEST OF CASING SHUT-OFF |  | REPORT ON REPAIRING WELL |          |
| REPORT ON RESULT OF PLUGGING WELL       |  | REPORT ON RECOMPLETION OPERATION            |  | REPORT ON Tests (Other)  |          |
|                                         |  |                                             |  | for casing leaks         | <b>X</b> |

September 21, 1953  
(Date)Monument, New Mexico  
(Place)

Following is a report on the work done and the results obtained under the heading noted above at the

Amerada Petroleum Corporation  
(Company or Operator)McKinley  
(Lease)Darrell W. Smith, Midland, Texas  
(Contractor)

Well No. 1 in the NW 1/4, NW 1/4 of Sec. 30

T. 18, R. 38, NMPM, Hobbs Pool, Lea County.

The Dates of this work were as follows: August 11, 1953 to September 7, 1953

Commission Memorandum to Hobbs Pool  
Operations dated 8-25-53.

Notice of intention to do the work ~~(was)~~ (was not) submitted on Form C-102 on \_\_\_\_\_, 19\_\_\_\_,  
(Cross out incorrect words)

and approval of the proposed plan ~~(was)~~ (was not) obtained.

## DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

- \* 1. Ran BHP survey after 24 hours shut in.
- \* 2. Ran Temperature Survey; found anomaly from 2100' to 2500'
- 3. Killed well and ran Baker Retainer to test oil string. Pressured up to 1900 psi on 7" casing for 30 minutes with no drop in pressure. Temperature anomaly is caused by Queens gas flow. Sweet gas is produced from 9-5/8" casing to supply gas to camp.

\* See attached reports.

Witnessed by W. G. Abbott Amerada Petroleum Corporation Petroleum Engineer  
(Name) (Company) (Title)

Approved: OIL CONSERVATION COMMISSION

I hereby certify that the information given above is true and complete to the best of my knowledge.

Name W. G. AbbottPosition District SuperintendentRepresenting Amerada Petroleum Corp.Address Monument, New Mexico

(Title)

(Date)

65 70 75 80 85 90 95 100

TEMPERATURE IN DEGREES F

12 1/2

23

DEPTH IN FEET

TEMPERATURE SURVEY

STATION NO. 1

30-13-18

HOBBS POOL

8-14-18

FIELD OFFICE