

1. DISTRICT		
2. TAP		
3. C.S.		
4. OFFICE		
5. RATOR		

MEXICO OIL CONSERVATION COMMISSION

C-102 and C-103
Effective 1-1-85

5a. Indicate Type of Lease
State ☐ ☐
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT - A" (FORM C-101) FOR SUCH PROPOSALS.

☐ OIL WELL ☐ GAS WELL ☐ OTHER	Name of Operator: Shell Oil Company Address of Operator: P.O. Box 991 Houston, TX 77001 Location of Well: UNIT LETTER 0 440 FEET FROM THE south LINE AND 2200 FEET FROM east LINE, SECTION 7 TOWNSHIP 18S RANGE 38E NMPM.
--	---

7. Unit Agreement Name
8. Farm or Lease Name
State
9. Well No.
1-A
10. Field and Pool, or Wildcat
Hobbs(G/SA)
12. County
Lea

15. Elevation (Show whether DF, RT, GR, etc.)
3674' (at top of csg.)

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

☐ REMEDIAL WORK ☐ PLUG AND ABANDON ☐ CHANGE PLANS ☐ RE-ENTER AND REPLUG	☐ AMENDED ☐ OTHER	☐ REMEDIAL WORK ☐ COMMENCE DRILLING OPNS. ☐ CASING TEST AND CEMENT JOB ☐ OTHER	☐ ALTERING CASING ☐ PLUG AND ABANDONMENT
--	--	---	---

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Dig out cellar. Remove marker. Rig up PU and reverse circulator.
2. Drill out wooden plug at 420' and CO to 4183'. Spot 100' Class "C" cmt plugs @4183'-4083'; 3370'-3270'; 3130'-3030'; 2420'-2320'.
3. Spot Class "C" cmt plug 1800'-1675'.
4. Spot Class "C" cmt plug 500'-300'.
5. Spot Class "C" cmt plug 175'-70'.
6. Spot 20' cmt plug at surface.
7. Weld plate over 20" csg. Install P&A marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

A.J. Fore A.J. Fore TITLE Supervisor Regulatory & Permits January 30, 1981

ED BY TITLE DATE
ITIONS OF APPROVAL, IF ANY: