

NEW MEXICO STATE LAND OFFICE
SANTA FE, NEW MEXICO

DEPARTMENT OF THE STATE GEOLOGIST
SANTA FE

NOTICE OF INTENTION TO ABANDON WELL

Notice must be given at least five days before work is to begin to the State Geologist or to the proper Oil and Gas Inspector. It is desirable that a representative of the Department of the State Geologist witness the plugging of wells being abandoned whenever possible. If changes in the proposed plan are considered advisable, a copy of this notice showing such changes will be returned to the sender. Submit this notice in duplicate.

Mr. **R. L. Halley, State Oil & Gas Insp.,**
Carlsbad, New Mexico. **Hobbs,** N. Mex., **Aug. 7** 19**30**

Dear Sir:

You are hereby notified that it is our intention to abandon Well
No. **1-A** in **SE 1/4** of Sec. **7** of Sec., T. **12 S**, R. **22 E**,
N. M. P. **Lease No. A-1646, Hobbs** Oil Field, **Lea** County.
We plan to commence work on **August 10th**, 19**30**.

The reasons for wishing to abandon the well are as follows:

Sulphur Water

The present condition of the well is as follows:

**Sulphur water struck at 4515' total depth 4520'. 7" O.D. Casing
Cemented at 4119'.**

The work which we propose to do in abandoning the well is as follows:

**Shut off sulphur with Lead Wool and Cement. Fill balance of hole
within 300' of top with mud. Set wood plug 300' from top to protect
surface water, and then fill with mud to surface.**

Approved Aug 14 30

Except as follows:

R. L. Halley
State Geologist or Oil and Gas Inspector.

Sincerely yours,

Landreth Production Corporation
Company or Operator.

By **L. A. Neal**

Position **Field Rep.**

Send communications regarding this well to

Name **as above**

Address **Box 996, Hobbs, New Mexico.**