

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-07341
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Lease Name or Unit Agreement Name N. HOBBS (G/SA) UNIT SECTION 18
2. Name of Operator SHELL WESTERN E & P INC. (4431 WCK)	8. Well No. 231
3. Address of Operator P.O. BOX 576, Houston, TX 77001-0576	9. Pool name or Wildcat HOBBS (G/SA)
4. Well Location Unit Letter K : 1980 Feet From The South Line and 1901 Feet From The West Line Section 18 Township 18-S Range 38-E NMMPM LEA County	10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3676' DF

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: OAP & AT <input checked="" type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) POOH w/ prod equip.
- 2) Spot 84 gals 15% HCl acid from 4135' up, using CIBP @ 4135'.
- 3) Per San Andres 4062' - 4103' w/ 2JSPF.
- 4) AT Grayburg/San Andres 3970' - 4103' w/ 4000 gals 15% HCl acid + 1200# rock salt, using pkr @ 3950'.
- 5) RIH w/ prod equip and return well to production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J.H. Smitherman J.H. Smitherman TITLE Prod. Administration Advisor DATE APR 20 1989

TYPE OR PRINT NAME

TELEPHONE NO.

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY

TITLE

APR 24 1989

DATE

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

APR 24 1996

OCB
HONORARY