State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

FILE IN TRIPLICATE	OIL CONSERVATION DIVISION					
DISTRICT 1 P.O. Box 1980, Hobbs, NM 88240	2040 Pacheco St.		WELL API NO	WELL API NO.		
DISTRICT II	Santa Fe, NM 87505		6 Indiana Ta	30-025-07345 5. Indicate Type of Lease		
811 S. 1st Street, Artesia, NM 88210			FED FED	STATE	FEE X	
DISTRICT III				Gas Lease No.	TEE X	
1000 Rio Brazos Rd, Aztec, NM 87410						
SUNDRY NOTICES AND REPORTS ON WELLS						
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			7. Lease Name	7. Lease Name or Unit Agreement Name		
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101 FOR SUCH PROPOSALS.)			NORTH HO	MODTH HODDS (C/SA) INIT		
1. Type of Well:	Te for foresett i kor oskes.	NORTH HO	NORTH HOBBS (G/SA) UNIT			
Oil Well	Gas Well Other	Section 18	Section 18			
2. Name of Operator				8. Well No. 321		
OCCIDENTAL PERMIAN LTD. 3. Address of Operator			O Pool nome	9. Pool name or Wildcat HORRS (G/SA)		
1017 W. Stanolind Rd., HOBBS, NM 88240 505/397-8200			9. Pool name o	or Wildcat	HOBBS (G/SA)	
4. Well Location						
Unit Letter G: 1980	Feet From The NORTH	Line and1980	Feet From The	EAST	Line	
Section 18	Township 18S	Range	38E NMI	PM	LEA County	
	10. Elevation (Show whether Di	F, RKB, RT GR, etc.)				
3653' GL 11. Check Appropriate Box to Indicate Nature of Notice Report or Other Data						
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:						
PERFORM REMEDIAL WORK PLUG AND ABANDON X REMEDIAL WORK ALTERING CASING						
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	G OPNS.		ANDONMENT [
PULL OR ALTER CASING	CASING TEST AND CEMENT JOB					
OTHER:		OTHER:				
12 Describe Proposed or Completed Operat	iona (Claruly state all autimost des)	<u> </u>				
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.						
Notify the NMOCD 24 hr before job. (393-6161)						
Notify the NMOCD 24 hr before job. (393-6161) Well is a TA'd well. CIBP set @4010'. Capped w/35' cmt. TOC @3975'. Circ Mud Gel from 3975' to 2800'. Spot cmt from 2800' to 2650'. Bot of Anhy @2725'. Circ Mud Gel from 2650' to 1680'. Spot cmt from 1650' to 1530'. Top of Anhy @1605'.						
Circ Mud Gel from 3975' to 2800'.						
Spot cmt from 2800' to 2650'. Bot of Anhy @2725'.						
Circ Mud Gel from 2650' to 1680'. Spot cmt from 1650' to 1530'. Top of Anhy @1605'.						
Circ Mud Gel from 1530' to 500'. TOC @510'.						
Perforate sqz hole @490'. Cicr cmt to surface.						
Spot cmt from 490' to Surface. Bot of 8-5/8" csg @433'.						
Spot cmt from 1650' to 1530'. Top of Anhy @1605'. Circ Mud Gel from 1530' to 500'. TOC @510'. Perforate sqz hole @490'. Circ cmt to surface. Spot cmt from 490' to Surface. Bot of 8-5/8" csg @433'. Install dry hole marker with well location 4' above ground level.						
82728						
I hereby certify that the information above is	true and complete to the heat of mule	naviladas and halist				
W +	- Will +	nowieuge and benei.				
SIGNATURE ATM	Filhi	TITLE SR. ENGR.	. TECH	DATE	09/09/2002	
TYPE OR PRINT NAME Robert Gi			TEI	LEPHONE NO.	505/397-8206	
(This space for State SeeGINAL SIGNED BY						
APPROVED BY GARY W. WINK CONDITIONS OF APPROVAL IF ANY: CONDITIONS OF APPROVAL IF ANY: CONDITIONS OF APPROVAL IF ANY:						
CONDITIONS OF APPROVAL IF ANY:						