## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

FILE IN TRIPLICATE	OIL CONSER'	VATION DIVISION	Reviseu 1-1-69
DISTRICT I P.O. Box 1980, Hobbs, NM 88240	2040 Pacheco St. Santa Fe, NM 87505		WELL API NO. 30-025-07348
DISTRICT II	Salita F	e, INIVI 67303	5. Indicate Type of Lease
811 S. 1st Street, Artesia, NM 88210			FED STATE FEE X
<u>DISTRICT III</u>			6. State Oil & Gas Lease No.
1000 Rio Brazos Rd, Aztec, NM 87410			
SUNDRY NOTICES AND REPORTS ON WELLS			
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"			7. Lease Name or Unit Agreement Name
(FORM C-101 FOR SUCH PROPOSALS.)			NORTH HOBBS (G/SA) UNIT
1. Type of Well: Oil Well	Gas Well Other T&A'd Well		7
2. Name of Operator	Gas Well Other T&A'd Well		Section 18 8. Well No. 311
OCCIDENTAL PERMIAN LTD.			S. Weil vid.
3. Address of Operator			9. Pool name or Wildcat HOBBS (G/SA)
1017 W. Stanolind Rd., HOBBS, NM 88240 505/397-8200  4. Well Location			
Unit Letter B : 990	Feet From The NORTH	Line and 2310 Fee	et From The EAST Line
Section 18	Township 18S	Range 38E	NMPM LEA County
	10. Elevation (Show whether DF, 3653' GL		BEA
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK	PLUG AND ABANDON X	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OP	NS. PLUG & ABANDONMENT
PULL OR ALTER CASING		CASING TEST AND CEMEN	NT JOB
OTHER:		OTHER:	
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work)			
SEE RULE 1103.			
Notify the NMOCD 24 hr before job. (393-6161)  Well is a TA'd well. CIBP set @4070'. Tag cmt @4030'.  Circ Mud Gel from 4030' to 3000'.  Spot cmt from 3000' to 2600'. Bot of Anhy @2800'. ** Top of cmt on 4.5" prod csg @2660'.  Circ Mud Gel from 2600' to 1800'.  Snot cmt from 1800' to 1400'. Top of Anhy @1600'.			
Well is a TA'd well. CIBP set @4070'. Tag cmt @4030'.			
Circ Mud Gel from 4030' to 3000'.			
Spot cmt from 3000' to 2600'. Bot of Anhy @2800'. ** Top of cmt on 4.5" prod csg @2660'.  Circ Mud Gel from 2600' to 1800'.			
Spot cmt from 1800' to 1400'. Top of Anhy @1600'.			
Circ Mud Gel from 1400' to 500'.			
Perforate sqz hole @500'. Cicr cmt to surface.			
Spot cmt from 500' to Surface. Bot of 8-5/8" csg @322'.  THE COMMISSION MUST BE NOTIFIED 24.			
Cut off wellhead and install dry hole		27 (28 (2011) 51 (51 (100)) 1 (100)	OF Contract of the contract of
		FERALIONS FOR THE C-1	03
	TO BE APPAUL	(±0.	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE Robert	Illet.	TITLE _ SR. ENGR. TEG	CH DATE 10/11/2002
TYPE OR PRINT NAME Robert G	ilbert		TELEPHONE NO. 505/397-8206
(This space for State Use)	V 10112 (1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
APPROVED BY	ORIGINAL SIGNEE:	BY TITLE	<b>0CT 1 1 2002</b>
CONDITIONS OF APPROVAL IF ANY:  OCHERO REPRESENTA THE MARK COM			
		(1) (1) (1) (1) (1) (1) (1) (1) (1) (1)	

