STATE OF NEW MEXICO

JERGY AND N	MINERALS DE	PARTMEN
NO 01 (0-		
DISTR	HOLTON	

OIL CONSERVATION DIVISION

		TION DIVISION	
DISTRIBUTION	P. O. BO	X 2088	Form C-103
SANTA FE	SANTA FE, NEW	MEXICO 87501	Revised 10-1-78
FILE			The Indiana Thursday
U.\$.G.\$.			5a. Indicate Type of Lesse
LAND OFFICE			State Fee X
OPERATOR			5. State Otl & Gas Lease No.
SUNDRY	NOTICES AND REPORTS ON	WELLS	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)		XIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII	
			7. Unit Agreement Name
OIL GAS WELL	OTHER: THIRD		N HODDS (C/GA) www.
Nume of Operator	INJECTOR		N. HOBBS (G/SA) UNIT
·			
SHELL OIL COMPANY		SECTION 19	
Address of Operator			9. Well No.
P. O. BOX 991, HOUSTON,	TX 77001		112
Location of Well			10. Field and Pool, or Wildcat
UNIT LETTER D 99	O FEET FROM THE NORTH	LINE AND 990 FEET FROM	HOBBS (G/SA)
WEST CETTON	19 18	S RANGE 38E NMPM.	
THE CINE, SECTION	TOWNSHIP	RANGENMPM.	
	15. Elevation (Show whether	DF. RT. GR. etc.)	12. County
		• • •	
	3671' DF		I LEA
Check Ap	propriate Box To Indicate N	ature of Notice, Report or Otl	ner Data
NOTICE OF INT	ENTION TO:	SUBSEQUENT	REPORT OF:
·	·		
CRFORM PEMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
EMPORABILY ABANDON		COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
THE OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB	
		OTHER	
CONVERT TO AN SA II	AND III u INJECTOR X	OTHER	L_
OTALA			
. Describe Proposed or Completed Open	ations (Clearly state all pertinent deta	ils, and give pertinent dates, including	estimated date of starting any proposed
work) SEE RULE 1103.			, , , , , , , , , , , , , , , ,

3671' DF	LEA
Check Appropriate Box To Indicate Nature of Notice, Report or O	ther Data
	IT REPORT OF:
"CRFORM PEMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
"ULL OR ALTER CASING CASING TEST AND CEMENT JOB	
OTHER CONVERT TO AN SA II AND III U INJECTOR X	
.T. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, includin	g estimated date of starting any proposed
work) SEE RULE 1103.	
1. RUPU. Pull tubing. Drill out to 4285'.	
2. Perf San Andres Zone II and IIIu 4127' - 4232'.	
3. Set pkr @4238'. Acidize open hole w/3000 gals 15% HCl NEA aci	d followed by ± 600#
benzoic acid flakes/graded rock salt.	id followed by ± 600#
4. Acidize perfs 4127' - 4232' w/2100 gals 15% HC1 NEA acid.	
5. Pull pkrs. Take injectivity test and complete.	
	;
•	
. 8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
(a.) introduction which is the missing the side of the book of my vindwiedge and belief.	
A I HODE CUMERUICON DEC /DUDMITTHING	HDE 2 1001
A. J. FORE TITLE SUPERVISOR REG. / PERMITTING	JUNE 2, 1981
TITLE TITLE	DATE
ONDITIONS OF APPROVAL, IF ANY: 1000 (1000)	
	·