L STRIBUTION	NEW MEXICO OIL CONSER	VATION COMMULTON	Supersects (c.) -16: and (-10) Libertive 1-1-65 (5a. indicate Type of Lense (bute) 2000 X
SUNDR	Y NOTICES AND REPORTS ON W	ELLS A TO A DIFFERENT RESERVE ROPOSALS.)	7, Vinit Agreement Seine
Circles Service Oil Com			Hardin
Base [9]9 - Midland, Te All - Son of Well Base LETTER D. S	190 FEET FROM THE North	LINE AND	Hobbs (G-SA)
	on <u>19</u> TOWNSHIP <u>18S</u> 15. Elevation (Show whether DI 3670! GR		12. County Lea
	Appropriate Box To Indicate Nation TO:		OF Other Data
PER THE SEVERIAL WORK		COMMENCE DRIVING OF5.2 CASING TEST AND CEMENT 10	X AUTERING DARE THE THE PEUG AND ARANDONMUNE THE THE X

(V. Leo, more reposed of Comp work) SEE RULE 1103.

0.T.D. 1255' Lime OPBTD 4253'. Workover complete. MIRU pulling unit, pulled rods, pump and tubing. Set a RBP @ 1603'. Located casing leak w/RTTS between 463' and 494'. Broke circulation to surface @ 4B/M at zero pressure. Tested casing above leak to 1000# - Held O.K. Dumped 1 ' of sand on top of RBP @ 1603' - 1589'. Squeezed down 5-1/2" casing w/200 sacks Class E w/29 CaCl cement(took 122 sacks to circulate to surface, 39 sacks in formation and 3h sacks in casing). Pressure tested 5-1/2" casing to 1000# for 15 minutes - Held O.K. Drilled cement 2251 - 2871 and pressure tested 5-1/2" casing to 1000# for 15 minutes - Held O.K. Drilled cement 287' - 519' and fell through and washed down to 550'. Set a RTTS @ 1529' and pressure tested RBP with 1200# for 15 minutes - Held O.K. Reset RTTS @ 869', 615' and 53 and pressure tested to 1200# each time - Held O.K. Reset RTTS @ 500' and pressure tested to 1200# - Held 0.K. Located hole in casing between 500' & 530'. Squeezed down 5-1/2" casing with 50 sacks Class C w/29 CaCl cement (40 sacks in formation and 10 sacks in casing). WOC 24 hrs. Tested 5-1/2" casing to 1000# - Held O.K. Drilled cement 4521 - 4891. Dropped out of cement @ 4891. Squeezed down 5-1/2" casing with 50 sacks Class H w/2% CaCl cement displaced down casing to 150' @ 1/2 B/M ( 900#. 40 sacks in formation, 10 sacks in casing. Pressure tested 5-1/2" casing to 1000# - Held O.K. Drilled cement @ 450' - 521'. Dropred out of cement @ 521'. Squeezed down 5-1/0" casing with 150 sacks Class H w/2% CaCl cement displaced down casing to 1501. 140 sack in formation, 10 sacks in casing. Pressure tested 5-1/2" casing to 1000#-Held C.K. Priled cement 4991 - 5291. Dropred out of cement @ 5291. Squeezed down 5-1/2" if. I hereby certify that the information above is true and complete to the best of my included on the

SIGNED	Efulden	Region Operation Manager	27 <b>6</b> 7 12	June 25,	1975	
	<u></u>			JUN	· .	- ,
A PLACYED BY		TITLE	1 K T			

cusing with 200 sacks Class C w/1/h# Flocele, 3# Gilsonite, 6# sand/sack and 3% CaCl cement displaced down casing to 350'. 180 sacks in formation, 20 sacks in casing. Tagged tor of curent @ 130' and pressure tested casing to 1000# - Held O.K. Drilled good cement @ 130'-500'. Dropred out of cement @ 520'. Soueezed down 5-1/2" casing with 200 sacks Class C w/1/h# Flocele, 5# Gilsonite, 6# sand and 3# salt/sack w/3% CaCl cement displaced down casing to 350'. 185 sacks in formation, 15 sacks in casing. Tagged top of cement @ 271' and pressure tested casing to 1000# - Held O.K. Drilled good cement @ 271' - 513'. Dropred out of cement "13'. Squeezed down 5-1/2" casing with 75 sacks Class C w/1/h# Flocele, 5# Gilsonite, 6# sand, 3% salt/sack and 3% CaCl followed by 80 sacks Class C and Calseal mixed 50-50 cement displaced class cement @ 350' - 520'. Dropped out of cement @ 520'. Pressure tested to 750# for 30 min. -8< 0.K. Cleaned out to 1603' and pulled RBP set @ 1603'. Cleaned out to PBTD 1253'. Ran 10.1.9 with a RTTS tool set @ 113' and Acidized thru San Andres Perfs 121' - 1218' w/2000 Class 15# NE HCl acid w/additives. Max. press. 600#, min. press. zero, AIR 5 B/M, ISIP Vac. 10.1.9 With a RTTS tool set @ 113' and Acidized thru San and set 2-3/8" OD tubing @ h2h1'. 10.2.9 Case and BHP and pumped on potential 17 BO + 15 BW/24 hrs. Grav. 31.8° GOR TSTM. This well was recompleted on 6-22-75.