

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-75

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

CIL WELL ☒ CAS WELL ☐ OTHER ☐

7. Unit Agreement Name
N. HOBBS (G/SA) UNIT

Name of Operator

SHELL WESTERN E&P INC.

8. Form or Lease Name
SECTION 19

Address of Operator

P. O. BOX 576, HOUSTON, TEXAS 77001 (WCK 4435)

9. Well No.
441

Location of Well

UNIT LETTER P 330 FEET FROM THE SOUTH LINE AND 330 FEET FROM
THE EAST LINE, SECTION 19 TOWNSHIP 18S RANGE 38E N.M.P.M.

10. Field and Pool, or Wildcat
HOBBS (G/SA)

15. Elevation (Show whether DF, RT, GR, etc.)

3657' DF

12. County
LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data:
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐

PLUG AND ABANDON ☐

CHANGE PLANS ☐

REMEDIAL WORK ☐

COMMENCE DRILLING OPERATIONS ☐

CASING TEST AND CEMENT JOB ☐

ALTERING CASING ☐

PLUG AND ABANDONMENT ☐

OTHER ☐

OAP & ACDZ ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. POH w/prod equip.
2. CO to PBTD @ 4242'.
3. Perf San Andres 4173' - 4221' (2 JSPF).
4. Acdz perms 4173' - 4236' w/1500 gals 15% HCl-NEA + 400# rock salt.
5. Install prod equip & return well to prod.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED A. J. FORE TITLE SUPERVISOR REG. & PERMITTING DATE 5-18-88

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT 1 SUPERVISOR

APPROVED BY _____ DATE MAY 23 1988