State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103

DATE

Revised 1-1-89 FILE IN TRIPLICATE OIL CONSERVATION DIVISION **DISTRICT I** 2040 Pacheco St WELL API NO. P.O. Box 1980, Hobbs, NM 88240 30-025-07369 Santa Fe, NM 87505 DISTRICT II 5. Indicate Type of Lease 811 S. 1st Street, Artesia, NM 88210 FED STATE DISTRICT III 6. State Oil & Gas Lease No. 1000 Rio Brazos Rd, Aztec, NM 87410 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A 7. Lease Name or Unit Agreement Name DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101 FOR SUCH PROPOSALS.) NORTH HOBBS (G/SA) UNIT 1. Type of Well: Oil Well Gas Well Other INJECTOR 2. Name of Operator 8. Well No 311 Oxy Permian LTD. 3. Address of Operator 9. Pool name or Wildeat HOBBS (G/SA) 1017 W. Stanolind Rd., HOBBS, NM 88240 505/397-8200 4. Well Location Unit Letter B Feet From The 1309 **NORTH** Line and Feet From The EAST Section 19 Township 18S Range NMPM 38E LEA County 10. Elevation (Show whether DF, RKB, RT GR, etc.) 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING **TEMPORARILY ABANDON** CHANGE PLANS COMMENCE DRILLING OPNS. PLUG & ABANDONMENT PULL OR ALTER CASING CASING TEST AND CEMENT JOB OTHER: OTHER: Cmt Squeeze Liner Top X 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. DO CIBP at 4150. 2. Perforate liner at 4065. 3. Squeeze Cement. 4. Set CIBP at 4050 and return well to TA'd status. Notify state of casing test I hereby certify that the complete to the best of my knowledge and belief. SIGNATURE DATE /0-10-01 TYPE OR PRINT NAME D. NELSON TELEPHONE NO. 505/397-8200 (This space for State Use)

TITLE

APPROVED BY

CONDITIONS OF APPROVAL IF ANY:

