

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-73

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- INJECTOR	7. Unit Agreement Name N. HOBBS (G/SA) UNIT
2. Name of Operator SHELL OIL COMPANY	8. Farm or Lease Name SECTION 19
3. Address of Operator P. O. BOX 991, HOUSTON, TEXAS 77001	9. Well No. 311
4. Location of Well UNIT LETTER B, 1309 FEET FROM THE NORTH LINE AND 2310 FEET FROM THE EAST LINE, SECTION 19 TOWNSHIP 18-S RANGE 38-E NMPM.	10. Field and Pool, or Whdcat HOBBS (G/SA)
15. Elevation (Show whether DF, RT, GR, etc.) 3667' GL	12. County LEA

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER CONVERT TO AN UPPER BASAL GRAYBURG INJ <input checked="" type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

PMX - 89

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- CO to 3930' \pm . Set RBP @ 3930'. Pressure test to 500 psi.
- Run CBL/CCL/VDL/GR log from 3930' to surface. Retrieve BP.
- Acidized w/7500 gals 15% HCl-NEA w/200# graded rock salt in gelled water.
- Set 7" Guiberson Uni-Packer VI @ 3852' \pm . Take injectivity test and complete.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE SUPERVISOR REG. & PERMITTING DATE MAY 14, 1982

APPROVED BY _____ TITLE _____ DATE MAY 17 1982

CONDITIONS OF APPROVAL, IF ANY: