Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICT I

OIL CONSERVATION DIVISION

WELL API NO.

P.O. Box 1980, Hoods, NM 88240	P.O. Box 2088		30-025-07371	
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa Fe, New Mexico 87504-2088		5. Indicate Type of Lease STATE	FEE X
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas Lease No.	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well:			7. Lease Name or Unit Agreement Name N. HOBBS (G/SA) UNIT SECTION 20	
OL X GAS WELL	OTHER			İ
2. Name of Operator Shell Western E&P Inc.			8. Well No. 341	
3. Address of Operator (WCK 4413))	9. Pool name or Wildcat	
P.O. Box 576 Houston, TX 77001-0576			HOBBS (G/SA)	
4. Well Location Unit LetterO :	330 Feet From The SOUTH	Line and	2310 Feet From The EAST	Line
Section 20 11. Check NOTICE OF IN	10. Elevation (Show whether I 3643' GR Appropriate Box to Indicate N	OF, RKB, RT, GR, etc.) Nature of Notice, Re	port, or Other Data	County
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	OPNS. PLUG AND ABAND	ONMENT [
		CASING TEST AND CEN	AENT JOB	
OTHER:		OTHER: ACE)	×
work) SEE RULE 1103. 12-16 TO 12-19-91: POH W/PROD EQMT. CO W/9	CSG SCRPR, POH. RAN GR/CNL, NEFE HCL. (DID NOT OAP.) INS	/ccl log. Acd exis	STING SA PERFS	

SIGNATURE CON CULLARY	TITLE W. F. N. KELLDORF	DATE
TYPE OR PRINT NAME W. F. N. KELLDORF		TELEPHONE NO. 713/870-3420
(This space for State Use) Orig. Signed by Geologist		Prof.
APTROVED BY	TIME -	DATE