

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form O-103
Revised 10-1-78

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO REEVALUATE OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE APPLICATION FOR PERMIT - FORM O-101 FOR SUCH PROPOSALS.

OIL WELL ☒ GAS WELL ☐ OTHER

Name of Operator
SHELL WESTERN E&P INC. (4431 WCK)
Address of Operator
P. O. BOX 576, HOUSTON, TEXAS 77001
Location of Well

7. Unit Agreement Name
N. HOBBS (G/SA) UNIT
8. Form of Lease Name
SEC. 27
9. Well No.
141

UNIT LETTER M 287 FEET FROM THE WEST LINE AND 330 FEET FROM THE SOUTH LINE, SECTION 27 TOWNSHIP 18-S RANGE 38-E N.M.P.M.

10. Field and Pool, or Window
HOBBS (G/SA)

11. Elevation (Show whether DF, RT, GR, etc.)
3644' GR

12. County
LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data.
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPERATIONS ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☒ OAP/AT	CASING TEST AND CEMENT JOBS ☐	OTHER ☐

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work.) SEE RULE 1103.

- 1) POOH w/ prod equip.
- 2) CO to 4257' (PBSD);
- 3) Perf Grayburg/San Andres 4032' - 4156' w/ 2JSPF.
- 4) Selectively AT Grayburg/San Andres 4032' - 4156' w/ 5600 gals 15% HCl + 1900# rock salt, using RPB's and pkr's.
- 5) RIH w/ prod equip and return well to production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED A. J. FORE TITLE SUPERVISOR REG. & PERMITTING

DATE DEC 9 1988

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

DATE JAN 04 1989

1000

1000

1000