Submit 3 Copies to Appropriate District Office

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICT I OIL CONSERVATION DIVISION WELL AFI NO. P.O. Box 1980, Hobbs, NM 88240 P.O. Box 2088 30-025-07411 **DISTRICT II** Santa Fe, New Mexico 87504-2088 P.O. Drawer DD, Artesia, NM 88210 5. Indicate Type of Lease FEE X STATE DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410 6. State Oil & Gas Lease No. SUNDRY NOTICES AND REPORTS ON WELLS ( DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A 7. Lease Name or Unit Agreement Name DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) N. HOBBS (G/SA) UNIT SECTION 28 1. Type of Well: OAS WELL WELL OTHER **INJECTOR** 2. Name of Operator 8. Well No. Shell Western E&P Inc. 441 3. Address of Operator 9. Pool name or Wildcat P.O. Box 576 Houston, TX 77001-0576 HOBBS (G/SA) 4. Well Location \_\_: \_\_\_660 Feet From The \_ Unit Letter P **EAST** 330 Feet From The SOUTH Line and Township 185 38E Range County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3642' GR Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data 11. NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING **TEMPORARILY ABANDON CHANGE PLANS** X COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT **PULL OR ALTER CASING** CASING TEST AND CEMENT JOB OAP & AT X OTHER: OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. AS AN ADDENDUM TO (& CHANGE OF PLANS FOR) THE ATTACHED SUNDRY NOTICE APPROVED 6/08/92. THE FOLLOWING OPERATIONS ARE PROPOSED IMMEDIATELY FOLLOWING STEP 9 & PRECEDING STEP 10: A. SET RBP @ +/-4090'. SPOT 1 BBL 15% HCL NEFE FROM 4075' TO 3975'. B. PERF SA 4045-72' (1 JSPF). C. AT NEW PERFS W/500 GAL 15% HCL NEFE. D. REL RBP & POH. I hereby certify that the information above is true and complete to the best of my knowledge and belief. TITLE TECH. MANAGER - ENVIR. ENG. DATE 9/11/92 SIGNATURE TYPE OR PRINT NAME W. F. N. KELLDORF TELEPHONE NO. 713/870-3797 (This space for State Life) ORIGINAL SIGNED BY JERRY SEXTON SEP 15'92 DISTRICT I SUPERVISOR

TITLE .

State of New Mexico Submit 3 Copies Form C-103 Energy, Minerals and Natural Resources Department to Appropriate District Office Revised 1-1-89 DISTRICT I OIL CONSERVATION DIVISION WELL API NO. P.O. Box 1980, Hobbs, NM 88240 P.O. Box 2088 30-025-07411 DISTRICT II Santa Fe. New Mexico 87504-2088 P.O. Drawer DD, Artesia, NM 88210 5. Indicate Type of Lease STATE FEE X DISTRICT III
1000 Rio Brazos Rd., Aziec, NM 87410 6. State Oil & Gas Lease No. SUNDRY NOTICES AND REPORTS ON WELLS ( DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A 7. Lease Name or Unit Agreement Name DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) N. HOBBS (G/SA) UNIT SECTION 28 Type of Well: VEL OTHER INJECTOR 2. Name of Operator & Well No. Shell Western E&P Inc. 441 3. Address of Operator (WCK 4587 9. Pool name or Wildcat P.O. Box 576 Houston, TX 77001-0576 HOBBS (G/SA) 4. Well Location Unit Letter P : 660 Feet From The EAST 330 Feet From The SOUTH \_\_ Line and \_\_ Line Section 28 Range Township 185 38E NMPM LEA 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3642' GR Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON **CHANGE PLANS** COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT **PULL OR ALTER CASING** CASING TEST AND CEMENT JOB OTHER: REP CSG LK OTHER:\_ 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 1. POH W/INJ EQMT. 2. CO TO TOL @ 3801'. 3. ISOLATE CSG LK USING PRES BU TECHNIQUE 4. IF 4-WAY SQZ @ 2545' IS THE ONLY LK, RUN 10' LONG INTERNAL CSG PATCH AS PER STEPS 6-8. 5. IF 4-WAY SQZ HOLES @ 2545' ARE NOT THE ONLY LK, CONSULT W/ENG. A CSG INSP LOG MAY BE RUN BEFORE PROCEEDING. 6. RIH W/API DRIFT GUAGE FOR 5-1/2 IN. 17# LNR TO 2600'. POH. 7. RIH W/30' 5-1/2 IN. WP TO ENSURE NO DOG LEG RESTRICTION. 8. SET 10' CSG PATCH ASSY FROM 2540-50'. 9. RIH W/5-1/2 IN. PKR & CONFIRM TBG/CSG ANN WILL NOT BUILD-UP PRES. 10. INST INJ EQMT, SETTING GUIB-UNI VI PKR @ +/-4030' (WITHIN TOP PERF @ 4102'). 11. PT TBG/CSG ANN TO 300# FOR 30 MIN. RTI. I hereby certify that the information aboys is true and complete to the best of my knowledge and belief.

TITLE TECH. MANAGER - ENVIR. ENG. DATE 6/02/92 SIGNATURE \_ TELEPHONE NO. 713/870-3426 TYPEORPRINTNAME W. F. N. KELLDORF (This space for State Use)

- TITLE -

ORIGINAL SIGNED BY JERRY SEXTON wie with a bitter comme

JUN 08'32

- DATE -

CONDITIONS OF APPROVAL, IF ANY: